

Wipe Date <u>9/15/00</u>		LEAK TEST CERTIFICATE	
DESCRIPTION OF DEVICE/SOURCE Model <u>500/C</u> Ser <u>2073</u> SOURCE 1 SOURCE 2 Material <u>CS-137 AM-241/DE</u> Source Ser <u>28266Q NJ02113</u> RSO Name <u>JOE FRANCIS</u> Telephone <u>(304)390-4277</u>		Do Not Write In This Space For HSI Use Only REMOVABLE ACTIVITY Be <u>0</u> Gam <u>0</u> Alpha <u>0</u> <u>0</u> uCi <u>0</u> uCi Humboldt Scientific By <u>DOTU</u> Date <u>9/29/00</u>	
5200174 Return Address Label Please Type or Print Clearly		<div style="border: 1px solid black; padding: 10px; text-align: center;"> American Geotech, Inc. 601 Ohio Avenue Charleston, West Virginia 25302 </div>	
		Instructions 1 Use wipe procedures as described in the device manual. 2 Enter all information under description. 3 Print or type return address in the space provided. 4 Wipe source (s) and put filter paper in the plastic bag. 5 Keep the middle copy and mail this form and bag to Humboldt. 6 Regulations require that sources with removable activity greater than 0.005 uCi be removed from service for repair and decontamination or disposal. Authorities must be notified.	
HUMBOLDT SCIENTIFIC INC. 5510 Pylon Drive, Raleigh, NC 27606, (919) 832-6509			