

I would find anything as this

To: BILL JONES UPB
MNB
P82186148
Publicly Available
FROM FSCANTHILL
4/9/86

To: FLOYD CAMPBELL, Chief, Section 1A

From: CHARLES BROOKS, Resident Inspector, BEMP

Subject: Potential Part 21 Relay
0277 95118

- REGIONAL ADMINISTRATOR
- DEPUTY ADMINISTRATOR
- ASST. TO ADMINISTRATOR
- DIRECTOR, DRP
- DIRECTOR, DRS
- DIRECTOR, DRSS
- DIRECTOR, RMA

ERIN GILMORE, A BORING EMPLOYEE UNDER CONTRACT AT THE

REDSTONE Arsenal in Huntsville, called to report a RELAY

PROBLEM THAT THEY HAD FOUND WITH A RELAY. THE RELAY

A POTTER & BRUNFIELD TIME DELAY RELAY P/N CKB-38-78180

SUPPLIED WITH A HALON FIRE PROTECTION SYSTEM. ERIN HAD

INFORMATION THAT SIMILAR SYSTEMS HAVE BEEN SUPPLIED TO

NUCLEAR POWER PLANTS. HE ALSO POINTED OUT THAT THE RELAY

IS NOT LIMITED TO FIRE PROTECTION SYSTEM APPLICATIONS. THE

RELAY HAS AN ABNORMALLY HIGH FAILURE RATE APPARENTLY

DUE TO RESISTOR OVERHEATING & BURN-OUT. POTTER & BRUNFIELD

HAS SUPPLIED REPLACEMENT SOLID STATE RELAYS TO THE ARMY.

IR 19

- 2 -

THIS INFORMATION MAY NEED TO BE EVALUATED FOR PAGE 21

REPUTABILITY AND MAY BE OF INTEREST TO THE VENDOR

PROGRAM BEAUNT. ADDITIONAL INFORMATION MAY BE OBTAINED

FROM ERNIE GILMORE AT THE REDSTONE RESERVE IN HUNTSVILLE,

ALABAMA; PHONE: 205/876-1723.