

April 12, 2001

MEMORANDUM TO: Donald C. Cook Nuclear Plant Manual Chapter 0350 Panel

FROM: Geoffrey E. Grant, Director, DRP */S/*

SUBJECT: MINUTES OF INTERNAL MEETING OF THE DONALD C. COOK
NUCLEAR PLANT MANUAL CHAPTER 0350 PANEL

The Donald C. Cook Nuclear Plant Manual Chapter 0350 Panel charter was announced on April 17, 1998, and most recently revised on January 10, 2001. These internal meetings are used to discuss significant technical and performance issues, NRC regulatory approach, and inspection resources and priorities. Attached for your information are the minutes from the internal meeting of the Inspection Manual Chapter 0350 Restart Panel held on April 5, 2001.

Docket Nos. 50-315; 50-316

Attachment: As stated

cc w/att: T. Bergman, NRR
S. Singh Bajwa, NRR
C. Craig, NRR
J. Stang, NRR
J. Thompson, NRR
J. Grobe, RIII
G. Grant, RIII
A. Vogel, RIII
M. Holmberg, RIII
B. Bartlett, RIII
D. Passehl, RIII
K. Coyne, RIII
J. Maynen, RIII
R. Walton, RIII
Docket Files

Please make this document publically available in ADAMS.

DOCUMENT NAME: G:\cook\dcc040501.mtgsum.wpd

To receive a copy of this document, indicate in the box: "C" = Copy without enclosure "E" = Copy with enclosure "N" = No copy

OFFICE	RIII		RIII		RIII		
NAME	Vogel/trn		Bajwa		Grant		
DATE	04/11/01		04/11/01		04/12/01		

OFFICIAL RECORD COPY

MEETING MINUTES: Internal MC 0350 Restart Panel Meeting
on the D. C. Cook Nuclear Plant

DATES: April 5, 2001

ATTENDEES:

S. Bajwa
T. Bergman
K. Coyne
C. Craig
A. Dunlop
G. Grant

M. Holmberg
J. Jacobson
J. Maynen
D. Passehl
J. Stang
J. Thompson
A. Vogel

Discussion Topics:

1. *Plant Status and Inspector Insights*

The resident inspectors provided a summary of plant activities. Both units were operating at full power. A small fire occurred earlier in the day on a main turbine seal oil pump skid. The licensee extinguished the fire within 15 minutes and was in the process of investigating the cause. The licensee reduced reactor power at the end of March 2001 to clean the main feedwater pump and main condenser waterboxes.

The inspectors discussed issues that were presented to the licensee during the most recent exit meeting, including recent findings regarding maintenance rule implementation.

2. *Discuss D.C. Cook Oversight*

The Panel discussed plans and specific licensee performance areas that need to be assessed to evaluate the adequacy of licensee long term corrective actions.

3. *Update on Containment Structural Issues*

Mr. Vogel provided an update on the containment structural issues at the plant. A public technical meeting in mid to late May 2001 to discuss the status of the containment issues is being considered.

4. *Licensing Issues*

Mr. Stang provided an update on licensing issues at the plant.

5. *Discuss April 10, 2001, Public Meeting*

The Panel reviewed the topics of the upcoming meeting to be held on April 10, 2001. The specific issues that will be discussed include operational performance of Units 1 and 2, corrective action program effectiveness, operability determination evaluation process and quality enhancements, and the status of long term corrective actions associated with maintenance rule implementation and engineering design control process improvements.