

LR:RH

NY 400
OCT 12 1961

Eastman Kodak Company
Kodak Park Works
Rochester 4, New York

Attention: Mr. John Mulder, Administrative
Assistant to General Manager

Gentlemen:

Thank you for your letter of September 21, 1961, informing us that you have corrected those deficiencies in your AEC licensed program which we brought to your attention in our letter of September 13, 1961. These matters will be reviewed during the next inspection of your facilities.

Your cooperation with us is appreciated.

Very truly yours,

Richard E. Cunningham, Chief
Enforcement Branch
Division of Licensing
and Regulation

bcc: Compliance Division, HO)
Compliance Division, NYOO)w/cpy ltr 9/13/61
Public Document Room)

OCT 18 1961

LR:EB

LR:EB

RH:med

RECunningham

10/6/61

RECEIVED
ITEM # 45

B145

(3)

EASTMAN KODAK COMPANY

ROCHESTER 4 NEW YORK

TELEPHONE
AREA ONE 21000

SEP. TWENTY 1951

Mr. Elmer R. Price, Assistant Director
Division of Licensing and Inventory
United States Atomic Energy Commission
Washington 25, D.C.

RE: 2210

Dear Sir:

Pursuant to the provisions of Section 161 of the "Atomic
Energy Act of 1946" and the "Atomic Energy Control Act of 1947",
State of Pennsylvania Regulations, we have given notice that all
violations described in your report of the AEC inspection
of April 15, 1951, regarding activities in connection with the
production of materials license number 2210-1, have been
corrected.

Specifically, with respect to the activities described under
license no. 2210-1:

1. As of August 2, 1951, collection of the
license was amended to read "the license number 2210-1, the
activities of which are described in the report of the AEC
inspection of April 15, 1951, regarding activities in connection
with the production of materials license number 2210-1, have
been corrected."

2. The small-60 sealed sources are now being tested
at the nearest accessible surface of six-month intervals. The
last such test was performed on August 20, 1951.

3. A "warning" label is now placed on the small-60
sources before they are placed in the small-60 sealed sources.

4. A sign "Small-60 sealed sources are not to be
used for work" is now placed in the small-60 sealed sources.

5. All other small-60 sealed sources are now being
tested at the nearest accessible surface of six-month intervals.


September 11, 1961

6) The storage well containing the 5 curie cobalt-60 source had been labeled as required by Section 20.125 (f)(1) and (f)(4).

With reference to license application:

7) The glove box containing radioactive material has been labeled as required by Section 20.125 (f)(4). This was done in the presence of the inspector on April 17, 1961.

Very truly yours,


John Maeder, Administrative
Assistant to General Manager
Atomic Waste Works

JN:jv
RFS