

June 15, 2001

Mr. Oliver D. Kingsley, President
Exelon Nuclear
Exelon Generation Company, LLC
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

SUBJECT: CORRECTION LETTER (TAC NOS. MB0807, MB0580, MB0581, MB0582, AND MB0583)

Dear Mr. Kingsley:

By letter dated January 12, 2001, the staff issued Amendment 115 to the license for Byron Station, Unit 1, reflecting the transfer of ownership of Byron Station from Commonwealth Edison Company to Exelon Generation Company, LLC. Page 1 of the license contained a typographical error. The corrected page is attached.

By letter dated May 17, 2001, the staff issued Amendment 120 to the licenses for Byron, Station, Units 1 and 2, and Amendment 114 to the licenses for Braidwood Station, Units 1 and 2. The amendments revised technical specification (TS) page 3.3.1 to delete the "Power Range Neutron Flux High Negative Rate" trip function from Table 3.3.1-1. The revised TS page was incorrectly identified as page 3.3.1-14. The correct TS page number should be 3.3.1-13. The corrected pages are attached. They should replace the present TS page 3.3.1-13. TS page 3.3.1-14 should be retained in its current form.

We apologize for any inconvenience that these errors may have caused.

Sincerely,

/RA/

George F. Dick, Jr., Project Manager, Section 2
Project Directorate III
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455,
STN 50-456, and STN 50-457

Enclosure: As stated

cc w/encl: See next page

O. Kingsley
Exelon Generation Company

Byron/Braidwood Stations

cc:

Ms. C. Sue Hauser, Project Manager
Westinghouse Electric Corporation
Energy Systems Business Unit
Post Office Box 355
Pittsburgh, Pennsylvania 15230

Attorney General
500 S. Second Street
Springfield, Illinois 62701

Illinois Department of Nuclear Safety
Office of Nuclear Facility Safety
1035 Outer Park Drive
Springfield, Illinois 62704

Joseph Gallo
Gallo & Ross
1025 Connecticut Ave., NW, Suite 1014
Washington, DC 20036

Exelon Generation Company, LLC
Byron Station Manager
4450 N. German Church Road
Byron, Illinois 61010-9794

Howard A. Learner
Environmental Law and Policy
Center of the Midwest
35 East Wacker Dr., Suite 1300
Chicago, Illinois 60601-2110

Exelon Generation Company, LLC
Site Vice President - Byron
4450 N. German Church Road
Byron, Illinois 61010-9794

U.S. Nuclear Regulatory Commission
Byron Resident Inspectors Office
4448 N. German Church Road
Byron, Illinois 61010-9750

U.S. Nuclear Regulatory Commission
Braidwood Resident Inspectors Office
35100 S. Rt. 53, Suite 79
Braceville, Illinois 60407

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
801 Warrenville Road
Lisle, Illinois 60532-4351

Mr. Ron Stephens
Illinois Emergency Services
and Disaster Agency
110 E. Adams Street
Springfield, Illinois 62706

Ms. Lorraine Creek
RR 1, Box 182
Manteno, Illinois 60950

Chairman
Will County Board of Supervisors
Will County Board Courthouse
Joliet, Illinois 60434

Chairman, Ogle County Board
Post Office Box 357
Oregon, Illinois 61061

Mrs. Phillip B. Johnson
1907 Stratford Lane
Rockford, Illinois 61107

Exelon Generation Company, LLC
Braidwood Station Manager
35100 S. Rt. 53, Suite 84
Braceville, Illinois 60407-9619

George L. Edgar
Morgan, Lewis and Bockius
1800 M Street, NW
Washington, DC 20036-5869

O. Kingsley
Exelon Generation Company, LLC

- 2 -

Byron/Braidwood Stations

Ms. Bridget Little Rorem
Appleseed Coordinator
117 N. Linden Street
Essex, Illinois 60935

Document Control Desk-Licensing
Exelon Generation Company, LLC
1400 Opus Place, Suite 500
Downers Grove, Illinois 60515

Exelon Generation Company, LLC
Site Vice President - Braidwood
35100 S. Rt. 53, Suite 84
Braceville, Illinois 60407-9619

Mr. William Bohlke
Senior Vice President, Nuclear Services
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, Illinois 60515

Mr. H. Gene Stanley
Operations Vice President
Mid-West Regional Operating Group
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, Illinois 60515

Mr. Christopher Crane
Senior Vice President
Mid-West Regional Operating Group
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, Illinois 60515

Mr. R. M. Krich
Director - Licensing
Mid-West Regional Operating Group
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, Illinois 60515

Exelon Generation Company, LLC
Regulatory Assurance Supervisor - Braidwood
35100 S. Rt. 53, Suite 84
Braceville, Illinois 60407-9619

Exelon Generation Company, LLC
Regulatory Assurance Supervisor - Byron
4450 N. German Church Road
Byron, Illinois 61010-9794

Mr. Robert Helfrich
Senior Counsel, Nuclear
Mid-West Regional Operating Group
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, Illinois 60515

Mr. Jeffrey Benjamin
Vice President - Licensing and
Regulatory Affairs
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, Illinois 60515

Mr. John Skolds
Chief Operating Officer
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, Illinois 60515

Mr. John Cotton
Senior Vice President - Operations Support
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, Illinois 60515

Mr. Oliver D. Kingsley, President
Exelon Nuclear
Exelon Generation Company, LLC
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

June 15, 2001

SUBJECT: CORRECTION LETTER (TAC NOS. MB0807, MB0580, MB0581, MB0582, AND MB0583)

Dear Mr. Kingsley:

By letter dated January 12, 2001, the staff issued Amendment 115 to the license for Byron Station, Unit 1, reflecting the transfer of ownership of Byron Station from Commonwealth Edison Company to Exelon Generation Company, LLC. Page 1 of the license contained a typographical error. The corrected page is attached.

By letter dated May 17, 2001, the staff issued Amendment 120 to the licenses for Byron, Station, Units 1 and 2, and Amendment 114 to the licenses for Braidwood Station, Units 1 and 2. The amendments revised technical specification (TS) page 3.3.1 to delete the "Power Range Neutron Flux High Negative Rate" trip function from Table 3.3.1-1. The revised TS page was incorrectly identified as page 3.3.1-14. The correct TS page number should be 3.3.1-13. The corrected pages are attached. They should replace the present TS page 3.3.1-13. TS page 3.3.1-14 should be retained in its current form.

We apologize for any inconvenience that these errors may have caused.

Sincerely,

/RA/

George F. Dick, Jr., Project Manager, Section 2
Project Directorate III
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455,
STN 50-456, and STN 50-457

Distribution:

PUBLIC ASTONE, RIII
PDIII/2

Enclosure: As stated

JZWOLINSKI/CCARPENTER

cc w/encl: See next page

AMENDIOLA
CROSENBERG
GDICK
MCHAWLA
OGC
ACRS

DOCUMENT NAME: C:\Program Files\Adobe\Acrobat 4.0\PDF Output\correction.letter.wpd
ML011640542

OFFICE	PM:PDIII/2		LA:PDIII/2		PM:PDIII/2		SC:PDIII/2	
NAME	GDICK		CROSENBERG		MCHAWLA		AMENDIOLA	
DATE	06/14/01		06/14/01		06/14/01		06/15/01	

OFFICIAL RECORD COPY