

From: Brian Holian
To: Bill Bateman, Edmund Sullivan, John Zwolinski
Date: Wed, Oct 25, 2000 11:29 AM
Subject: revised comments on LLTF memo

Ted,

some other wording changes to what I sent you this morning...we took some words right out of the special inspection cover letter...

Would like to see the whole memo when you have it together.

thanks

Brian

"The attached lessons-learned report provides a number of generic technical and process recommendations that apply to the industry and the NRC. There is a recommendation directed to Con Edison which supports the conclusions of the August 31, 2000, NRC Special Inspection Report on the IP2 steam generator tube failure. The lessons-learned report reiterates the significant performance issues (as described in the August 31, 2000, NRC Special Inspection Report) related to how Con Edison implemented its steam generator inspection program during the 1997 plant outage. Principally, those performance issues were associated with the licensee not recognizing and taking appropriate corrective actions for significant conditions adverse to quality that affected the steam generator inspection program (e.g., not adequately accounting for conditions which adversely affected the detectability of, and increased the susceptibility to, tube flaws). The licensee specific deficiencies identified in the special inspection report and any further interactions between NRC and Con Edison relative to those deficiencies are being addressed under the NRC's oversight process."

CC: DCL, HJM1, JTW1, WDL

①

4/29