

From: Stephanie Coffin *NRC*
 To: Jefferey Harold *R-III*
 Date: Thu, May 11, 2000 9:45 AM
 Subject: Re: IP2 tube plugging issues (missed tubes)

Jeff,

Can you set up a phone call today with ConEd to discuss your email message below and also to discuss their investigation into the TTS inspection where 3 of the 8 indications were called by only one analyst. We need to understand ASAP what the licensee is doing on this issue. Please try to set up a phone call for today, 3 pm or later is good.

Thanks,

Stephanie

>>> Jefferey Harold 05/10 1:15 PM >>>

We have been notified that Con Ed has determined that 6 tubes from the list of tube to be plugged were missed. The missed tubes are as follows

SG 21 None
 SG 22 1 tube - R4C14
 SG 23 4 tubes - R3C70
 - R11C62
 - R12C64
 - R4C53
 SG 24 1 tube - R10C87

Con Ed, Westinghouse, and other contractor are reviewing the issue. They have reached a preliminary conclusion as to how the tubes were missed. In addition, they are verifying that no others were missed.

Would you like for meet to set up a conference call with Con Ed to discuss this issue? If so when.

CC: Caius Dodd, David Lew, Edmund Sullivan, Emmett Murphy, Pete Eselgroth, William Raymond

103
130
M/62