

March 14, 2002

Dr. William G. Vernetson
Director of Nuclear Facilities
Department of Nuclear and
Radiological Engineering
P. O. Box 11830
University of Florida
Gainesville, FL 32611

SUBJECT: CORRECTION TO NRC INSPECTION REPORT NO. 50-83/2001-201

Dear Dr. Vernetson:

This letter refers to inspection report No. 50-83/2001-201 dated February 27, 2002.

Due to an administrative error, the date, referred to in Section 6.a of the report, for revision fourteen of your security plan was incorrect. The correct date is September 25, 1997, rather than the September 28, 2001, date cited in the report.

We apologize for any inconvenience this may have caused. Should you have any questions concerning this letter, please contact Mr. Stephen Holmes at 301-415-8583.

Sincerely,

/RA/

Patrick M. Madden, Section Chief
Research and Test Reactors Section
Operating Reactor Improvements Program
Division of Regulatory Improvement Programs
Office of Nuclear Reactor Regulation

Docket No. 50-83
License No. R-130

cc: Please see next page

University of Florida

Docket No. 50-83

cc:

Mr. James S. Tulenko, Chairman
Nuclear Engineering Sciences
Department
University of Florida
202 Nuclear Sciences Center
Gainesville, FL 32611

Administrator
Department of Environmental Regulation
Power Plant Siting Section
State of Florida
2600 Blair Stone Road
Tallahassee, FL 32301

State Planning and Development
Clearinghouse
Office of Planning and Budgeting
Executive Office of the Governor
The Capitol Building
Tallahassee, FL 32301

Mary E. Clark, Chief
Office of Radiation Control
Department of Health
and Rehabilitative Services
1317 Winewood Boulevard
Tallahassee, FL 32999

Test, Research, and Training
Reactor Newsletter
University of Florida
202 Nuclear Sciences Center
Gainesville, FL 32611

March 14, 2002

Dr. William G. Vernetson
Director of Nuclear Facilities
Department of Nuclear and
Radiological Engineering
P. O. Box 11830
University of Florida
Gainesville, FL 32611

SUBJECT: CORRECTION TO NRC INSPECTION REPORT NO. 50-83/2001-201

Dear Dr. Vernetson:

This letter refers to inspection report No. 50-83/2001-201 dated February 27, 2002.

Due to an administrative error, the date, referred to in Section 6.a of the report, for revision fourteen of your security plan was incorrect. The correct date is September 25, 1997, rather than the September 28, 2001, date cited in the report.

We apologize for any inconvenience this may have caused. Should you have any questions concerning this letter, please contact Mr. Stephen Holmes at 301-415-8583.

Sincerely,
/RA/

Patrick M. Madden, Section Chief
Research and Test Reactors Section
Operating Reactor Improvements Program
Division of Regulatory Improvement Programs
Office of Nuclear Reactor Regulation

Docket No. 50-83
License No. R-130
cc: Please see next page

DISTRIBUTION:

PUBLIC	RORP r/f	TDragoun	PDoyle	WEresian
Plsaac	SHolmes	CBassett	MMendonca	FGillespie
WBeckner	EHylton	AAdams	BDavis (Ltr.only O5-A4)	

ACCESSION NO.: ML020710731

TEMPLATE #: NRR-106

OFFICE	RORP:LA		RORP:RI		RORP:SC	
NAME	EHylton:rdrr		SHolmes		PMadden	
DATE	03/ 14 /2002		03/ 14 /2002		03/ 14 /2002	

C = COVER

E = COVER & ENCLOSURE
OFFICIAL RECORD COPY

N = NO COPY