

June 17, 2002

Mr. Marc-André Charette
Regulatory Affairs Senior Associate
MDS Nordion
447 March Road
Ottawa, Ontario
Canada K2K 1X8

Dear Mr. Charette:

As you requested in your letter dated December 6, 2001, we have corrected the registration certificates numbers NR-0220-D-121-S, and NR-0220-S-124-S, based on information submitted in your letter. Thank you for bringing these errors to our attention. Copies of the corrected certificates are enclosed.

Please be advised that you must manufacture and distribute the product in accordance with the statements and representations contained in your application and subsequent correspondence, with enclosures thereto, and the information set out in your registration certificate. As a general rule, you must request and obtain an amendment to the certificate before you make changes or modifications to the information submitted to obtain the certificate.

Please read over the registration certificate in its entirety and notify us immediately of any errors or omissions. You are obligated to notify us promptly in writing should you decide to no longer manufacture or offer service support for the product.

Please be aware that, as a holder of an NRC registration, you may be subject to the NRC's licensing and inspection fees in accordance with 10 CFR Part 170, and annual fees in accordance with 10 CFR Part 171. If you have any questions concerning the fee requirements, please contact the License Fee and Accounts Receivable Branch at (301) 415-7554.

If you have any questions, please contact me at (301) 415-7038 or Dr. John Jankovich at (301) 415-7904.

Sincerely,

/RA/

William R. Ward, P.E.
Mechanical Engineer
Materials Safety and Inspection Branch
Division of Industrial and
Medical Nuclear Safety
Office of Nuclear Material Safety
and Safeguards

Enclosure: As stated
cc w/encl: RJones, LFARB

June 17, 2002

Mr. Marc-André Charette
Regulatory Affairs Senior Associate
MDS Nordion
447 March Road
Ottawa, Ontario
Canada K2K 1X8

Dear Mr. Charette:

As you requested in your letter dated December 6, 2001, we have corrected the registration certificates numbers NR-0220-D-121-S, and NR-0220-S-124-S, based on information submitted in your letter. Thank you for bringing these errors to our attention. Copies of the corrected certificates are enclosed.

Please be advised that you must manufacture and distribute the product in accordance with the statements and representations contained in your application and subsequent correspondence, with enclosures thereto, and the information set out in your registration certificate. As a general rule, you must request and obtain an amendment to the certificate before you make changes or modifications to the information submitted to obtain the certificate.

Please read over the registration certificate in its entirety and notify us immediately of any errors or omissions. You are obligated to notify us promptly in writing should you decide to no longer manufacture or offer service support for the product.

Please be aware that, as a holder of an NRC registration, you may be subject to the NRC's licensing and inspection fees in accordance with 10 CFR Part 170, and annual fees in accordance with 10 CFR Part 171. If you have any questions concerning the fee requirements, please contact the License Fee and Accounts Receivable Branch at (301) 415-7554.

If you have any questions, please contact me at (301) 415-7038 or Dr. John Jankovich at (301) 415-7904.

Sincerely,

/RA/

William R. Ward, P.E.
Mechanical Engineer
Materials Safety and Inspection Branch
Division of Industrial and
Medical Nuclear Safety
Office of Nuclear Material Safety
and Safeguards

Enclosure: As stated
cc w/encl: RJones, LFARB

Distribution:

SSD-01-54 NR-0220-D-121-S NR-0220-S-124-S
ADAMS ML021680438

To receive a copy of this document, indicate in the box:

"C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	MSIB	E	MSIB	E				
NAME	WWard WRW		JJankovich JPJ					
DATE	6/ 17 /2002		6/ 17 /2002					

OFFICIAL RECORD COPY