

May 29, 2003

Mr. Michael R. Kansler, President
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION REGARDING REQUEST FOR
RELAXATION FROM ORDER ESTABLISHING INTERIM INSPECTION
REQUIREMENTS OF REACTOR VESSEL HEADS, INDIAN POINT NUCLEAR
GENERATING UNIT NO. 3 (TAC NO. MB8163)

Dear Mr. Kansler:

In a letter dated March 27, 2003, Entergy Nuclear Operations, Inc. (ENO) requested a relaxation from certain requirements in an Order issued by the U.S. Nuclear Regulatory Commission (NRC) on February 11, 2003 (EA-03-009). Specifically, ENO requested a relaxation for Indian Point Nuclear Generating Unit No. 3 from the inspection coverage when performing ultrasonic testing of each reactor vessel head penetration nozzle from 2 inches above the J-groove weld to the bottom of the nozzle, as specified in Section IV.C(2)(b)(i) of the Order.

The NRC staff is reviewing the information provided in the March 27 submittal and has determined that additional information is needed to complete its review. The specific questions are found in the enclosed request for additional information (RAI). During a telephone call on May 20, 2003, the ENO staff indicated that a response to the RAI would be provided within 90 days.

If you should have any questions, please do not hesitate to call me.

Sincerely,

/RA/

Patrick D. Milano, Sr. Project Manager, Section 1
Project Directorate 1
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-286

Enclosure: RAI

cc w/encl: See next page

May 29, 2003

Mr. Michael R. Kansler, President
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION REGARDING REQUEST FOR
RELAXATION FROM ORDER ESTABLISHING INTERIM INSPECTION
REQUIREMENTS OF REACTOR VESSEL HEADS, INDIAN POINT NUCLEAR
GENERATING UNIT NO. 3 (TAC NO. MB8163)

Dear Mr. Kansler:

In a letter dated March 27, 2003, Entergy Nuclear Operations, Inc. (ENO) requested a relaxation from certain requirements in an Order issued by the U.S. Nuclear Regulatory Commission (NRC) on February 11, 2003 (EA-03-009). Specifically, ENO requested a relaxation for Indian Point Nuclear Generating Unit No. 3 from the inspection coverage when performing ultrasonic testing of each reactor vessel head penetration nozzle from 2 inches above the J-groove weld to the bottom of the nozzle, as specified in Section IV.C(2)(b)(i) of the Order.

The NRC staff is reviewing the information provided in the March 27 submittal and has determined that additional information is needed to complete its review. The specific questions are found in the enclosed request for additional information (RAI). During a telephone call on May 20, 2003, the ENO staff indicated that a response to the RAI would be provided within 90 days.

If you should have any questions, please do not hesitate to call me.

Sincerely,

/RA/

Patrick D. Milano, Sr. Project Manager, Section 1
Project Directorate 1
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-224 and 50-286

Enclosure: RAI

cc w/encl: See next page

DISTRIBUTION

PUBLIC	R. Laufer	S. Little	S. Bloom
PDI-1 Reading	P. Milano	P. Eselgroth, RGN-I	OGC
C. Holden	T. Chan	E. Reichelt	ACRS

Accession Number: ML031490691

OFFICE	PDI-1:PM	PDI-1:LA	EMCB:SC	PDI-1:SC	
NAME	PMilano	SLittle	TChan	RLaufer	
DATE	5/21/03	5/22/03	5/22/03	5/28/03	

OFFICIAL RECORD COPY

Indian Point Nuclear Generating Unit No. 3

cc:

Mr. Jerry Yelverton
Chief Executive Officer
Entergy Operations
1340 Echelon Parkway
Jackson, MS 39213

Mr. John Herron
Senior Vice President and
Chief Operating Officer
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. Fred Dacimo
Vice President - Operations
Entergy Nuclear Operations, Inc.
Indian Point Nuclear Generating Unit 3
295 Broadway, Suite 1
P. O. Box 308
Buchanan, NY 10511-0308

Mr. Dan Pace
Vice President Engineering
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. James Knubel
Vice President Operations Support
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. Joseph DeRoy
General Manager Operations
Entergy Nuclear Operations, Inc.
Indian Point Nuclear Generating Unit 3
295 Broadway, Suite 3
P. O. Box 308
Buchanan, NY 10511-0308

Mr. John Kelly
Director - Licensing
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Ms. Charlene Faison

Licensing
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. Harry P. Salmon, Jr.
Director of Oversight
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. James Comiotes
Director, Nuclear Safety Assurance
Entergy Nuclear Operations, Inc.
Indian Point Nuclear Generating Unit 3
295 Broadway, Suite 3
P.O. Box 308
Buchanan, NY 10511-0308

Mr. John McCann
Manager, Licensing and Regulatory Affairs
Entergy Nuclear Operations, Inc.
Indian Point Nuclear Generating Unit 2
295 Broadway, Suite 1
P. O. Box 249
Buchanan, NY 10511-0249

Resident Inspector's Office
U.S. Nuclear Regulatory Commission
295 Broadway, Suite 3
P.O. Box 337
Buchanan, NY 10511-0337

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. John M. Fulton
Assistant General Counsel
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Indian Point Nuclear Generating Unit No. 3

cc:

Ms. Stacey Lousteau
Treasury Department
Entergy Services, Inc.
639 Loyola Avenue
Mail Stop: L-ENT-15E
New Orleans, LA 70113

Mr. William M. Flynn, President
New York State Energy, Research, and
Development Authority
17 Columbia Circle
Albany, NY 12203-6399

Mr. J. Spath, Program Director
New York State Energy, Research, and
Development Authority
17 Columbia Circle
Albany, NY 12203-6399

Mr. Paul Eddy
Electric Division
New York State Department
of Public Service
3 Empire State Plaza, 10th Floor
Albany, NY 12223

Mr. Charles Donaldson, Esquire
Assistant Attorney General
New York Department of Law
120 Broadway
New York, NY 10271

Mayor, Village of Buchanan
236 Tate Avenue
Buchanan, NY 10511

Mr. Ray Albanese
Executive Chair
Four County Nuclear Safety Committee
Westchester County Fire Training Center
4 Dana Road
Valhalla, NY 10592

Mr. Ronald Schwartz
SRC Consultant
64 Walnut Drive
Spring Lake Heights, NJ 07762

Mr. Ronald J. Toole
SRC Consultant
Toole Insight
605 West Horner Street
Ebensburg, PA 15931

Mr. Charles W. Hehl
SRC Consultant
Charles Hehl, Inc.
1486 Matthew Lane
Pottstown, PA 19465

Mr. Alex Matthiessen
Executive Director
Riverkeeper, Inc.
25 Wing & Wing
Garrison, NY 10524

Mr. Paul Leventhal
The Nuclear Control Institute
1000 Connecticut Avenue NW
Suite 410
Washington, DC, 20036

Mr. Karl Copeland
Pace Environmental Litigation Clinic
78 No. Broadway
White Plains, NY 10603

Jim Riccio
Greenpeace
702 H Street, NW
Suite 300
Washington, DC 20001

REQUEST FOR ADDITIONAL INFORMATION

REGARDING RELAXATION FROM NRC ORDER EA-03-009

INDIAN POINT NUCLEAR GENERATING UNIT NO. 3 (IP3)

DOCKET NO. 50-286

In a letter dated March 27, 2003, Entergy Nuclear Operations, Inc. (the licensee) requested relaxation from the performing ultrasonic testing (UT) of each reactor pressure vessel head penetration nozzle (i.e., nozzle base material), from 2 inches above the J-groove weld to the bottom of the nozzle. The licensee stated that the bottom 0.75 inch of the nozzle is threaded and designed to accommodate the installation of guide funnels. Due to the threads, the licensee stated that meaningful UT test data cannot be obtained in this region, due to dispersion of the UT signal. The licensee proposes to perform UT from 2 inches above the J-groove weld to the top of the threaded region, which is approximately 0.75 inch above the bottom of the nozzle.

The U.S. Nuclear Regulatory Commission (NRC) staff has the following questions regarding the information provided in the relaxation request:

1. The licensee stated that a structural evaluation was performed for the IP3 nozzles.

Provide the applicable technical data (i.e., operating stress levels, crack growth analysis, hoop stresses, etc.) which supports the conclusion that the area in the threaded region is insignificant.

2. The licensee stated that if cracking is detected above the threaded region, and extends into the threaded area, other nondestructive examination (NDE) methods would be used to determine the extent of cracking.

Identify the particular NDE methods that would be utilized, and provide the justification why this additional NDE would not be proposed/performed as an alternative to the requirements in the Order.

Enclosure