

August 8, 2003

LICENSEE: STP Nuclear Operating Company

FACILITY: South Texas Project, Unit 1

SUBJECT: SUMMARY OF HEADQUARTERS, REGION IV, AND SOUTH TEXAS PROJECT NUCLEAR OPERATING COMPANY TELEPHONE CONFERENCE OF JULY 10, 2003, REGARDING SOUTH TEXAS PROJECT, UNIT 1, BOTTOM-MOUNTED INSTRUMENTATION LEAKAGE ISSUE; STATUS OF ACTIVITIES (TAC NO. MB8435)

On July 10, 2003, the U. S. Nuclear Regulatory Commission (NRC) Headquarters and Region IV staff held a telephone conference with STP Nuclear Operating Company (STPNOC), the licensee for South Texas Project (STP), Units 1 & 2. The conference call was a continuation of the ongoing discussions and was a follow up of the licensee's activities following the discovery at Unit 1 of an apparent leakage at the interface of the reactor vessel bottom head mounted instrumentation (BMI) penetrations nos. 1 and 46. Enclosure 1 is a list of participants. Enclosure 2 is the agenda for the telephone conference.

At this phone call the licensee went through a list of ongoing activities, outlining the status as follows:

- The licensee will capture boat samples, including the weld area where a helium bubbles release was sighted.
- The licensee is set to start taking the boat samples on July 11th and will ship the samples to Framatome promptly.
- The licensee will provide NRC with schedules for the sample processing.
- The licensee plans to release a letter tomorrow which provides information regarding actions taken and commitments made. The letter is undergoing final internal licensee reviews.
- Regarding the finite element analyses of fatigue factors, the summary of the fatigue calculations does not include a safety factor of 4. The safety factor of 2 will be used for the cumulative usage factor calculation.
- All of the guide tubes have been cleaned and fittings were replaced at the seal table.
- The root cause analyses are progressing.

- Primary Water Stress Corrosion Cracking does not appear to be the root cause for the crack indications. Fabrication is the more likely cause. The licensee will continue to study both options until satisfied with the conclusion.
- As part of its post-repair monitoring program, the licensee will commit to do penetration ultrasonic testing (UT) inspections again at the end of the Unit 1 current inservice inspection interval, sometime in 2008 or 2009.
- Unit 2 visual examination has shown no problems. The licensee will complete the Unit 2 penetration UT examination in 2005.
- The wastage will be monitored on the repair nozzles. The licensee is discussing with the NRC its post-repair monitoring decisions.

The phone call ended with a reminder that the July 17, 2003, call will not be held due to the third NRC/STPNOC meeting on that same day.

/RA/

Mohan C. Thadani, Sr. Project Manager, Section 1
Project Directorate IV
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-498

Enclosures: 1. List of Participants
2. Telephone Conference Agenda

cc: see next page

LIST OF PARTICIPANTS

STPNOC/NRC TELEPHONE CONFERENCE

JULY 10, 2003

Licensee's Participants

Dave Rencurrel	Manager, Plant Operations
Chet McIntyre	BMI Engineering
Tripp Frahm	BMI Project Manager
Ed Conway	Public Information
Wayne Harrison	Licensing

NRC Participants

Headquarters

Mohan Thadani
Carol Moyer
Mark Hartzman
Stephanie Coffin
Jack Foster
Bob Gramm
Chris Gratton

Region IV

Bill Johnson
Tom Farnholtz
Russ Bywater
Mike Runyan

STPNOC/NRC

TELEPHONE CONFERENCE AGENDA

JULY 10, 2003

1.	Desired Outcomes & Agenda	Review	Harrison	1400 CDT (2)
2.	Overall status of Unit 1	Discuss	Rencurrel	(2)
3.	Status of repair activities	Discuss	Frahm	(5)
4.	Root cause and inspection and monitoring plan	Discuss	McIntyre	(10)
5.	Boat sample activities	Discuss	McIntyre	(5)
6.	Status of Engineering and Licensing Actions	Discuss	Harrison	(10)
7.	Schedule for next call or other communications and feedback on call (+/Δ)	Discuss	Harrison	(5)

- Primary Water Stress Corrosion Cracking does not appear to be the root cause for the crack indications. Fabrication is the more likely cause. The licensee will continue to study both options until satisfied with the conclusion.
- As part of its post-repair monitoring program, the licensee will commit to do penetration ultrasonic testing (UT) inspections again at the end of the Unit 1 current inservice inspection interval, sometime in 2008 or 2009.
- Unit 2 visual examination has shown no problems. The licensee will complete the Unit 2 penetration UT examination in 2005.
- The wastage will be monitored on the repair nozzles. The licensee is discussing with the NRC its post-repair monitoring decisions.

The phone call ended with a reminder that the July 17, 2003, call will not be held due to the third NRC/STPNOC meeting on that same day.

/RA/

Mohan C. Thadani, Sr. Project Manager, Section 1
Project Directorate IV
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-498

Enclosures: 1. List of Participants
2. Telephone Conference Agenda

cc: see next page

DISTRIBUTION:

PUBLIC

PDIV-1 Reading

RidsNrrAdpt (BSheron/MKotzalas)	RidsRgn4MailCenter (AHowell)	WCullen
RidsNrrDlpm (LMarsh/ELeeds)	RidsNrrDe (RBarrett)	SLee
RidsNrrDlpmLpdiv (HBerkow)	RidsNrrDeEmcb (BBateman)	JFoster
RidsNrrDlpmLpdiv-1 (RGramm)	RidsNrrDeEmcb (SCoffin)	SBloom
RidsNrrPMMThadani	RidsNrrDeEmeb (DTerao)	EAndruszkiewicz
RidsNrrPmWReckley	MMitchell	CMoyer
RidsNrrLAMMcAllister	ESullivan	AHisert
RidsOgcRp	MHartzman	KManoly
RidsNrrDssa (SBlack/MJohnson)	RidsAcrsAcnwMailCenter	
TMensah	MFields, EDO	

ADAMS Accession No.: ML032100321

*via e-mail

NRC-001

OFFICE	PDIV-1/PM	PDIV-1/LA	RIV	PDIV-1/SC
NAME	MThadani:sab	MMcAllister	WJohnson*	RGramm
DATE	8/08/2003	8/08/2003	8/08/2003	8/08/2003

OFFICIAL RECORD COPY

South Texas Project, Unit 1

cc:

Mr. Cornelius F. O'Keefe
Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P. O. Box 910
Bay City, TX 77414

A. Ramirez/C. M. Canady
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, TX 78704

Mr. L. K. Blaylock
Mr. W. C. Gunst
City Public Service Board
P. O. Box 1771
San Antonio, TX 78296

Mr. C. A. Johnson/A. C. Bakken
AEP Texas Central Company
P. O. Box 289
Mail Code: N5022
Wadsworth, TX 77483

INPO
Records Center
700 Galleria Parkway
Atlanta, GA 30339-3064

Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

D. G. Tees/R. L. Balcom
Texas Genco, LP
P. O. Box 1700
Houston, TX 77251

Judge, Matagorda County
Matagorda County Courthouse
1700 Seventh Street
Bay City, TX 77414

A. H. Gutterman, Esq.
Morgan, Lewis & Bockius
1111 Pennsylvania Avenue, NW
Washington, DC 20004

Mr. T. J. Jordan, Vice President
Engineering & Technical Services
STP Nuclear Operating Company
P. O. Box 289
Wadsworth, TX 77483

S. M. Head, Manager, Licensing
Nuclear Quality & Licensing Department
STP Nuclear Operating Company
P. O. Box 289, Mail Code: N5014
Wadsworth, TX 77483

Environmental and Natural Resources
Policy Director
P. O. Box 12428
Austin, TX 78711-3189

Jon C. Wood
Matthews & Branscomb
112 East Pecan, Suite 1100
San Antonio, TX 78205

Arthur C. Tate, Director
Division of Compliance & Inspection
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756

Brian Almon
Public Utility Commission
William B. Travis Building
P. O. Box 13326
1701 North Congress Avenue
Austin, TX 78701-3326

cc:

Susan M. Jablonski
Office of Permitting, Remediation
and Registration
Texas Commission on
Environmental Quality
MC-122
P.O. Box 13087
Austin, TX 78711-3087

Mr. Terry Parks, Chief Inspector
Texas Department of Licensing
and Regulation
Boiler Division
P. O. Box 12157
Austin, TX 78711

Mr. Ted Enos
4200 South Hulen
Suite 630
Ft. Worth, Texas 76109

Mr. James J. Sheppard
President and Chief Executive Officer
STP Nuclear Operating Company
South Texas Project Electric
Generating Station
P. O. Box 289
Wadsworth, TX 77483