

# NRC INSPECTION MANUAL

IIPB

---

Change Notice 03-028

---

## DELETED:

	<u>Number</u>	<u>Date</u>
1.	----	----
2.	----	----
3.	----	----
4.	----	----
5.	----	----
6.	----	----
7.	----	----
8.	----	----
9.	----	----
10.	----	----

## TRANSMITTED:

<u>Number</u>	<u>Date</u>
IMC 2509	08/06/03
IP 35301	08/06/03
IP 50090	08/06/03
IP 50100	08/06/03
IP 51053	08/06/03
IP 51055	08/06/03
IP 51061	08/06/03
IP 70304	08/06/03
TI 2500/020	08/06/03
TI 2515/111	08/06/03

TRAINING: No special training requirements have been identified for any documents issued with this change notice.

REMARKS: IMC 2509 (Browns Ferry Unit 1 Restart Project Inspection Program) is issued to address closure of open items, regulatory concerns, inspection requirements, temporary discontinuance of ROP during the BF1's restart, adoption of the traditional-form of enforcement since the SDP is not applicable from a risk perspective during the BF1 restart, and the transition into the ROP on a cornerstone by cornerstone basis.

IP 35301, "Preoperational Testing - Quality Assurance"  
IP 70304, "Engineered Safety Features Test - Preoperational Test Procedure Review"  
IP 70315, "Engineered Safety Features Test - Preoperational Test Witnessing"

IP 70322, "Preoperational Test Results Evaluation - ESF"  
IP 50090, "Pipe Support and Restraint Systems"  
IP 50100, "Heating, Ventilating, and Air Conditioning Systems"  
IP 51053, "Electrical Components and Systems - Work Observation"  
IP 51055, "Electrical Components and Systems - Record Review"  
IP 51061, "Electrical Cable - Procedure Review"  
TI 2055/020, "Inspection to Determine Compliance with ATWS Rule  
10 CFR 50.62"  
TI 2515/111, "Electrical Distribution System Followup Inspection"

The above inspection procedures and temporary instructions had been previously deleted, but are now re-activated for use with the BF1 restart program.

DISTRIBUTION: Standard

END