



- NOTES:**
1. THE INFORMATION ON THIS DWG. IS BASED ON CE DWG. E-6378-210-162.
  2. REFERENCE CE DWG. E-6378-210-161E-BL.
  3. WASTE TANK INLET TRAPS ARE TO BE DRAINED PERIODICALLY. AFTER DRAINING, REFILL TRAP FOR 2T-20A BY RUNNING WATER IN HOT MACHINE SHOP SLOLLERY SINK FOR 3 MINUTES & REFILL 2T-20B TRAP SIMILARLY FROM SAMPLE PREP. ROOM SINK (ZONES E-7 & E-4).
  4. ALL RADIOACTIVE SYSTEMS PIPE DRAINS SHALL BE HEADERED TOGETHER WHERE APPROPRIATE AND RUN TO THE DRAIN COLLECTION HEADER.
  5. 2SV-2008 IS PROVIDED WITH DUAL COILS PER VP 6880-M-2132A-59-3.
  6. 2PP-2068 IS A REMOVABLE FLANGED CONNECTION TO ALLOW PRESSURIZATION OF THE END OF 2CV-2008-1 OPEN TO CONTAINMENT FOR LLRT PER PROCEDURE 2304.15. THE FIXTURE SHALL BE REMOVED UPON COMPLETION OF LLRT.
  7. DELETED