

LICENSE NO. 37-30804-02DOCKET NO. 030-36239

APPENDIX C

C.5 Checklist for Determining When Significant Licensing Action Has Taken Place That May Require An Additional Onsite Inspection**CHECKLIST FOR DETERMINING WHEN SIGNIFICANT LICENSING ACTION HAS TAKEN PLACE THAT MAY REQUIRE AN ADDITIONAL ONSITE INSPECTION**

If recent licensing actions have resulted in one of the following, regional management should determine the need for performing an onsite inspection prior to the next routine inspection:

1. Does the licensing action result in increased authorization for types and quantities of radioactive material that could result in a significant potential for increased radiation exposure to the public and occupational workers?

☒ No
☐ Yes (*Describe*)

Note: This can be identified by a change to a higher priority, i.e., from a Priority 2 to a Priority 1 license. Another "rule-of-thumb" for identifying a significant change in this area would be an increase in the authorized quantity from a millicurie amount to a curie amount.

2. Does the licensing action authorize a physical move of a facility or authorize use at a temporary job site(s)?

☒ No
☐ Yes

3. Does the licensing action authorize satellite facilities where material will be used or stored?

☒ No
☐ Yes

4. Does the licensing action increase the types of uses or disposal (incineration) of radioactive materials?

☒ No
☐ Yes

5. Does the licensing action significantly increase the number of authorized users?

☒ No
☐ Yes