

U.S. NUCLEAR REGULATORY COMMISSION		Conversation Date: 3/1/2005
TELEPHONE CONVERSATION RECORD		Time: 10:00am
Mail Control No.:	License No.:	Docket No.:
	37-20684-01	030-20718
Licensee/Applicant Participant(s):	Organization:	Telephone No.:
United Defense York, Pa		717-225-4781
Person(s) Calling: M. Davis RSO		
Subject: Identified and corrected violations		
<p>Summary:</p> <p>Michael Davis RSO called and stated that they had identified 2 violations where they possessed H-3 alignment sites at locations not authorized by their license. The first one in January 1994 when 22 vehicles were transferred to them from the Army at Laymont Furnace, PA and these vehicles still contained tritium alignment devices about 3 curies each. Again in 1998, 42 vehicles of which 35 contained H-3 alignment devices were transferred from the Army to Laymont Furnace, Pa site. IN each case the licensee's personnel removed the alignment sites from the vehicles and sent them to the US Army Letterkinney Depot in PA, which has a license to posses the H-3 He was reporting the violation and wanted to know what to do. Told him to write up a report and we would review it at next inspection. He may need to amend the license to add Laymont Furnace, PA site as a place of use</p>		
Action Required/Taken: put into ADAMS		
Prepared By: Johansen	Date: 3/1/2005	