

TELEPHONE CONVERSATION RECORD	Date: June 14, 2005	Time: 11:30
Mail Control No.: N/A Inspection No.: N/A	License No.: 37-30196-01	Docket No.: 030-33750
Person Calling: J. Donald Cammerata, Radiation Safety Officer	Licensee: Burle Industries, Inc.	Telephone No.: 717-295-6696
Person Calling: Steven Courtemanche/(610) 337-5075		
Subject: Telephone report of a missing source.		
<p><u>Summary:</u> Mr. Cammerata called to ask me about the status of the license amendment changing the Radiation Safety Officer since he will be retiring by the end of the month. I stated that I would be taking the action since I was caught up on my work. Mr. Cammerata then asked me what needed to be done concerning a missing sealed source. The source contained about 27 millicuries of tritium encased in lucite. The licensee was cutting down on its inventory and in the process of packaging 700 sources for shipment, noted that one of the 1442 on-site could not be accounted for. The inventory was performed on June 10, 2005, and he did not know when the last time the source was used or seen. The licensee has performed a check of the facilities and could not find it. I informed Mr. Cammarata that he needed to call the NRC Operations Center and provide them with the information he gave me and, in addition, provide the manufacturer's name, sealed source model number and serial number, if any, along with any corrective actions. If the licensee knows how the licensed material was lost, that information should be provided as well. The licensee is also required to provide the NRC a thirty-day written report in accordance with 10 CFR 20.2201(b) which details what information is required. I offered to help if he or his successor needed information on what needed to be put in the written report.</p>		
Action Required/Taken: Place into ADAMS.		
Prepared by Steven Courtemanche	Date: June 14, 2005	