



MAY 18 1962

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

1. LICENSEE Aluminum Corporation of America Alcoa Research Laboratories Freeport Road New Kensington, Pennsylvania		2. REGIONAL OFFICE REGION I, DIVISION OF COMPLIANCE U. S. ATOMIC ENERGY COMMISSION 376 HUDSON STREET NEW YORK 14, NEW YORK	
3. LICENSE NUMBER(S) 37-7653-2			
4. INSPECTION FINDINGS		Date of Inspection <u>May 10, 1962</u>	
<input checked="" type="checkbox"/> A. No item of noncompliance was found.			
<input type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b)			
<input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c)(1)			
<input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)			
<input type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)			
<input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f)(1) or (f)(2)			
<input type="checkbox"/> G. Storage containers were not properly labeled to show the quantity, date of measurement, or kind of radioactive material in the containers. 10 CFR 20.203(f)(4)			
<input type="checkbox"/> H. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)			
<input type="checkbox"/> I. Form AEC-3 was not properly posted. 10 CFR 20.206(c)			
<input type="checkbox"/> J. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a)			
<input type="checkbox"/> K. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b)			
<input type="checkbox"/> L. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.41, 40.61 or 70.51			
<input type="checkbox"/> M. Records of leak tests were not maintained as prescribed in your license.			
		 AEC Representative	
5. LICENSEE'S ACKNOWLEDGMENT			
The AEC representative has explained and I understand the items of noncompliance listed above, if any. The items of noncompliance will be corrected within the next 30 days.			
		 Licensee Representative	
Date _____			

COPIES: ☐ LICENSEE; ☒ COMPLIANCE AREA; ☐ DIV. OF LIC. & REG.; ☐ DIV. OF COMPLIANCE (2)