

R

FEB 27 1964

COLLECT  
X

USAEC, GERMANTOWN, MARYLAND  
DONALD A. HUSSEBAUMER, CHIEF  
SOURCE AND SPECIAL NUCLEAR MATERIALS BR.  
DIVISION OF LICENSING AND REGULATION

UNITED NUCLEAR CORPORATION  
CHEMICALS DIVISION  
ROUTE 21-A  
HEMATITE, MISSOURI

ATTENTION: MR. R. W. SHEARER

THIS CONFIRMS TELECON ON FEBRUARY 26, 1964. REQUIRE FOLLOWING INFORMATION  
CONCERNING APPLICATION FOR SMR LICENSE AT RHODE ISLAND.

1. THE DIMENSIONS OF THE FLASH TANK SHOWN AT POSITION A-5 DRAWING A-903.
2. WITH TWO VALVES IN THE LINES LEADING FROM FILTRATE RECIRCULATION PUMP (1-P-17), Dwg. A-903, IT APPEARS CREDIBLE THAT CONCENTRATED LIQUOR MAY BE PUMPED INADVERTENTLY TO THE WASTE TREATMENT TANKS, OR THAT CONCENTRATED SOLUTION MAY DRAIN THROUGH TWO VALVES FROM THE OR LIQUOR HOLD TANKS TO THE WASTE TREATMENT TANKS. PLEASE DELINEATE YOUR PROCEDURES FOR CONTROLLING THESE PROBLEMS.
3. DESCRIPTION OF EQUIPMENT FEATURES AND OTHER CONTROLS WHICH WILL PREVENT DRAWING SOLUTION BACKING UP INTO THE AIR & STEAM LINES AND ENTERING THE BOILER, AIR RECEIVERS OR OTHER UNSAFE GEOMETRY CONTAINERS IN THE EVENT OF EITHER STEAM OR AIR PRESSURE FAILURE.
4. WHAT ARE THE SIZES OF THE VARIOUS LINE FILTERS LABELED F1 ON YOUR DRAWINGS.
5. ON DRAWING A-904, SHOULD NOT LINE 1" ANG ENTERING SCRUB SOLUTION TANK (1-U-3) BE LABELED "FROM PUMP 1-P-20" INSTEAD OF PUMP 1-P-21 ALSO, SHOULD NOT LINE 1" 242 BE LABELED "CONTINUED ON DWG. A-903" INSTEAD OF DWG. A-904 AND SHOULD NOT

RLayfield  
RM. 414  
7457

Copy furnished field office  
III

Completed  
G-2

FEB 27 1964

UNITED NUCLEAR CORPORATION

2

1 THE 1/2" LA-4 BE LABELED "FROM PUMPS (1-P-2A & B)" INSTEAD OF (1-2A & B)

THE FIRST QUESTION RELATES DIRECTLY TO NUCLEAR SAFETY.

6. IN ADDITION TO WATER AND ACID LINES ENTERING THE STRIP ACID TANKS (1-D-6A & B) WHAT OTHER MATERIAL MAY ENTER THESE TANKS FROM THE HOSE LINES. DWG, A-904 IS NOT CLEAR ON THIS POINT. REFERENCE: DLR:ILL : 70-520

WASHINGTON, D.C.  
U.S. VICTIMS' REL. COMM.

1964 FEB 27 10 21

DIAGNOSTIC SERVICE  
RECEIVED