

September 14, 2005

Mr. David H. Oatley, Vice President
and General Manager
Diablo Canyon Power Plant
P.O. Box 56
Avila Beach, CA 93424

SUBJECT: DIABLO CANYON POWER PLANT, UNIT NO. 2 - RESPONSE TO NUCLEAR
REGULATORY COMMISSION BULLETIN 2003-02, "LEAKAGE FROM REACTOR
PRESSURE VESSEL LOWER HEAD PENETRATIONS AND REACTOR
COOLANT PRESSURE BOUNDARY INTEGRITY" (TAC NO. MC0535)

Dear Mr. Oatley:

On August 21, 2003, the U.S. Nuclear Regulatory Commission (NRC) issued NRC Bulletin 2003-02, "Leakage from Reactor Pressure Vessel Lower Head Penetrations and Reactor Coolant Pressure Boundary Integrity," to the industry. This bulletin informed addressees that current methods of inspecting the reactor pressure vessel (RPV) lower heads may need to be supplemented with bare-metal visual inspections in order to detect reactor coolant pressure boundary leakage. The bulletin also requested these addressees to provide the NRC with information related to inspections that have been performed to verify the integrity of the RPV lower head penetrations.

The bulletin requested that addressees provide a description of the RPV lower head penetration inspection program that would be implemented at their respective plants during the next, and subsequent, refueling outages. This description was to include the extent of the inspection, the inspection methods to be used, the qualification standards for the inspection methods, the process used to resolve the source of findings of boric acid deposits or corrosion, the inspection documentation to be generated, and the basis for concluding that their plant satisfied applicable regulatory requirements related to the structural, and leakage integrity of the RPV lower head penetrations.

By letter dated November 18, 2003, Pacific Gas and Electric Company (PG&E) provided its response to this request for Diablo Canyon Power Plant, Unit 2. PG&E reported that it had performed a bare-metal visual examination of the RPV lower head and of all 58 penetrations in February 2003. There was no evidence of RPV lower head penetration leakage observed. Additionally, in its letter, PG&E committed to perform a bare-metal visual examination of the RPV lower head during the Fall 2004 refueling outage and every third refueling outage thereafter until such a time that industry experience or regulatory guidance indicates a modification of the inspection frequency or method is warranted. PG&E stated that this examination scope would include all 58 RPV lower head penetrations, including 100 percent of the circumference of each penetration as it enters the RPV lower head, and the areas surrounding the tubes. Hence, PG&E is requested to make it a regulatory commitment and notify the NRC in writing of any significant change to this commitment in the future.

The bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, a description of the as-found condition of the lower head, any findings of relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits, and any corrective actions taken as a result of indications found.

By letter dated February 8, 2005, PG&E provided a summary of its inspection results at Diablo Canyon Power Plant, Unit 2. PG&E reported that during the Unit 2 12th refueling outage, completed on December 16, 2004, it had performed a bare-metal visual examination of all 58 RPV lower head penetrations, including 100 percent of the circumference of each penetration as it enters the RPV lower head, and the areas surrounding the penetrations. PG&E did not observe any evidence of RPV lower head penetration leakage.

Based on its review of PG&E's responses to NRC Bulletin 2003-02, the NRC staff finds that PG&E has met the reporting requirements of the bulletin for Diablo Canyon Power Plant, Unit 2. Accordingly, TAC No. MC0535 is closed for Diablo Canyon Power Plant, Unit 2.

Sincerely,

/RA/

Girija Shukla, Project Manager, Section 2
Project Directorate IV
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-323

cc: See next page

The bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, a description of the as-found condition of the lower head, any findings of relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits, and any corrective actions taken as a result of indications found.

By letter dated February 8, 2005, PG&E provided a summary of its inspection results at Diablo Canyon Power Plant, Unit 2. PG&E reported that during the Unit 2 12th refueling outage, completed on December 16, 2004, it had performed a bare-metal visual examination of all 58 RPV lower head penetrations, including 100 percent of the circumference of each penetration as it enters the RPV lower head, and the areas surrounding the penetrations. PG&E did not observe any evidence of RPV lower head penetration leakage.

Based on its review of PG&E's responses to NRC Bulletin 2003-02, the NRC staff finds that PG&E has met the reporting requirements of the bulletin for Diablo Canyon Power Plant, Unit 2. Accordingly, TAC No. MC0535 is closed for Diablo Canyon Power Plant, Unit 2.

Sincerely,

/RA/

Girija Shukla, Project Manager, Section 2
Project Directorate IV
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-323

cc: See next page

DISTRIBUTION:

PUBLIC	SMonarque	RGramm	OGC	LFeizollahi
PDII-1 RF	GShukla	LMarsh	ACRS	DCollins
PDIV-2 RF	GCheruvenki	ESullivan	RidsRgn4MailCenter (BJones)	

ADAMS ACCESSION NUMBER: ML05

NRR-106

OFFICE	PDIV-2/PM	PDIV-2/LA	PDII/PM	EMCB	PDIV-2/SC(A)
NAME	GShukla	LFeizollahi	SMonarque	ESullivan	DCollins
DATE	9/14/05	9/14/05	9/9/05	09/06/2005	9/14/05

E:\Filenet\ML052580510.wpd

OFFICIAL RECORD COPY

Diablo Canyon Power Plant, Units 1 and 2

cc:

NRC Resident Inspector
Diablo Canyon Power Plant
c/o U.S. Nuclear Regulatory Commission
P.O. Box 369
Avila Beach, CA 93424

Sierra Club San Lucia Chapter
c/o Henriette Groot
1000 Montecito Road
Cayucos, CA 93430

Ms. Nancy Culver
San Luis Obispo
Mothers for Peace
P.O. Box 164
Pismo Beach, CA 93448

Chairman
San Luis Obispo County Board of
Supervisors
Room 370
County Government Center
San Luis Obispo, CA 93408

Mr. Truman Burns
Mr. Robert Kinoshian
California Public Utilities Commission
505 Van Ness, Room 4102
San Francisco, CA 94102

Diablo Canyon Independent Safety
Committee
ATTN: Robert R. Wellington, Esq.
Legal Counsel
857 Cass Street, Suite D
Monterey, CA 93940

Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
Harris Tower & Pavillion
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

Richard F. Locke, Esq.
Pacific Gas & Electric Company
P.O. Box 7442
San Francisco, CA 94120

City Editor
The Tribune
3825 South Higuera Street
P.O. Box 112
San Luis Obispo, CA 93406-0112

Mr. Ed Bailey, Chief
Radiologic Health Branch
State Department of Health Services
P.O. Box 997414 (MS 7610)
Sacramento, CA 95899-7414

Mr. James D. Boyd, Commissioner
California Energy Commission
1516 Ninth Street (MS 31)
Sacramento, CA 95814

Mr. James R. Becker, Vice President
Diablo Canyon Operations
and Station Director
Diablo Canyon Power Plant
P.O. Box 3
Avila Beach, CA 93424

Jennifer Tang
Field Representative
United States Senator Barbara Boxer
1700 Montgomery Street, Suite 240
San Francisco, CA 94111

Mr. Gregory M. Rueger
Senior Vice President, Generation and
Chief Nuclear Officer
Pacific Gas and Electric Company
Diablo Canyon Power Plant
P.O. Box 3
Avila Beach, CA 93424