



Entergy Operations, Inc.
River Bend Station
5485 U.S. Highway 61N
St. Francisville, LA 70775
Tel 225 381 4157
Fax 225 635 5068
dlorfin@entergy.com

David N. Lorfing
Manager-Licensing

SAFEGUARDS INFORMATION

September 29, 2005

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
11555 Rockville Pike
Rockville, MD 20852-2738
301-415-7000

SUBJECT: Mitigating Strategies Request for Additional Information
TAC No. MC7078 and MC7079
River Bend Station
Docket No. 50-458
License No. NPF-47

RBG-46482
RBF1-05-0165
File Codes: G9.5, G9.20.6.10

Dear Sir or Madam:

On September 8, 2005, River Bend Station conducted a teleconference with NRC so that you could more fully understand, through our responses to your requests for additional information (RAIs), the enhancements that have been implemented at the site related to B.5.b. Subsequently, the NRC requested by letter dated September 14, 2005, that Entergy provide written responses to these RAIs. The attachment provides the responses for River Bend Station to the RAIs clarifying our original submittal dated May 31, 2005. A PGP encrypted copy has also been provided via e-mail.

If you have any questions, please contact Mr. Bill Fountain @ 225-381-4625.

Sincerely,


David N. Lorfing
Manager - Licensing

DNL/WJF/dhw

Enclosure - RBS RAI Questions With Responses

NOTICE: The attachment to this letter contains SAFEGUARDS INFORMATION. Upon separation of the attachment, this page becomes DECONTROLLED.

SAFEGUARDS INFORMATION

SIGN: 1227

SAFEGUARDS INFORMATION

RBG-46482

Page 2 of 2

cc: (via encrypted e-mail)

Mr. Michael K. Webb, NRR
Mr. Robert A. Gramm, NRR

(w/o attachments)

Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Dr. Suite 400
Arlington, TX 76011-8064

Mr. Peter J. Alter
P. O. Box 1050
St. Francisville, LA 70775

NOTICE: The attachment to this letter contains SAFEGUARDS INFORMATION.
Upon separation of the attachment, this page becomes DECONTROLLED.

SAFEGUARDS INFORMATION

SICN: 1227