

Open Generic Communication TACs (PA No. 101122CA/B)

Summary Report as of 09/30/2005

TAC NO.	TAC TITLE	AGE	LEAD ORG
MC8341	BL: Potential Impact of Chemical Precipitants on Emerg Recirc During DBAs at PWRs (Karwoski-DE/Markley-DIPM)	1	DE
MC7021	GL: Assurance of Industry Implementation of Key Shutdown Voluntary Initiatives (Pohida-DSSA/Markley-DIPM)	5	DSSA
MC6496	GL: Failures of Inaccessible/Underground Cables That Disable Accident Mitigation Systems (Koshy-DE/Markley-DIPM)	7	DE
MC5657	GL: Grid Reliability and the Impact on Plant Risk and the Operability of Offsite Power (Lazevnick-DE/Markley-DIPM)	9	DE
MC6893	GL: Managing Gas in Emergency Core Cooling Systems (Lyon-DSSA/Markley-DIPM)	5	DSSA
MC6498	GL: Post-Fire Safe-Shutdown Circuit Analysis Spurious Actuations (Wolfgang-DSSA/Markley-DIPM)	7	DSSA
MC6921	GL: Potentially Degraded HEMYC/MT Electrical Raceway Fire Barrier Systems (Lavretta-DSSA/Markley-DIPM)	5	DSSA
MC6635	GL: Primary Water Stress Corrosion Cracking in Butt Welds (Sullivan-DE/Markley-DIPM)	6	DE
MC2470	GL: Steam Generator Tube Integrity and Associated Technical Specifications (Karwoski-DE/Markley-DIPM)	19	DE
MC8089	IN: Boiling Water Reactor (BWR) Containment Steel Torus Shell Cracking (Ashar-DE/King-DIPM/)	2	DE
MC8100	IN: Design Deficiency in Pressurizer Heaters (Graves-R4/Tabatabai-DIPM)	2	R4
MC7265	IN: Kewaunee - Plant Design May Not Mitigate Consequences of Turbine Building Flooding (Kozak-R3/Telson-DIPM)	4	R3
MC6949	IN: Movement of Supports in Steam Generators (Yoder-DE/Hodge-DIPM)	5	DE
MC8322	IN: Product Alert for Fire Hydrant (Qualls-DSSA/Roquecruz-DIPM)	1	DSSA
MC8529	IN: Secondary Piping Rupture Accident at Mihama Power Station Unit 3 (Lauron-DE/Hodge-DIPM)	0	DE
MC7614	RIS: Anticipated Transients Developing into More Serious Events (Miranda-DSSA/Markley-DIPM)	3	DSSA
MC7617	RIS: Application of Alternative Source Term (Drozd-DSSA/Markley-DIPM)	3	DSSA
MC6738	RIS: Clarification of NRC Guidelines for Control of Heavy Loads (Jones-DSSA/Markley-DIPM)	6	DSSA
MC6266	RIS: Clarification of Post-Fire Safe-Shutdown Circuit Regulatory Requirements (Radlinski-DSSA/Markley-DIPM)	7	DSSA
MC6782	RIS: Control of Sensitive Unclassified Non-Safeguards Info Related to Nucl Pwr Reactors (Reckley-DLPM/Markley-DIPM)	6	DLPM
MC8203	RIS: Endorsement of NEI Guidance "Enhancements to Emergency Preparedness Programs ..." (Sullivan-NSIR/Markley-DIPM)	2	NSIR
MC6900	RIS: NRC Staff Position on 10 CFR 50.36, "Tech Spec", Instrument Setting Requirements" (Gratton-DLPM/Markley-DIPM)	5	DLPM
MC6647	RIS: Recent Experience from BWR Instability Events (Huang-DSSA/Markley-DIPM)	6	DSSA
MC5858	RIS: RIS 2002-15, Rev 1-NRC Approval of Comm Data Encryption Sys for Electronic Trans of SGI (Lee-NSIR/Markley-DIPM)	8	NSIR
MC5252	RIS: Scope of For-Cause Fitness-for-Duty Testing Required by 10 CFR 26.24(a)(3) (Canady-NSIR/Markley-DIPM)	10	NSIR
MC5826	RIS: Issuance of NUREG-1482, Rev 1-Guidelines for Inservice Testing At Nucl Pwr Plants (Unikewicz-DE/Markley-DIPM)	8	DE
MC6734	RIS: RIS 2003-18, Sup 2 - Use of NEI 99-01, Methodology for Dev of Emerg Actn Levels, Rev 4 (Johnson-NSIR/Markley-DIPM)	6	NSIR