

NRC FORM 699 (9-2003)		U.S. NUCLEAR REGULATORY COMMISSION		DATE <div style="text-align: center;">11/21/2005</div>
CONVERSATION RECORD				TIME <div style="text-align: center;">10:15am</div>
NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU Donald Warren		TELEPHONE NO.		TYPE OF CONVERSATION <input type="checkbox"/> VISIT <input type="checkbox"/> CONFERENCE <input checked="" type="checkbox"/> TELEPHONE <input type="checkbox"/> INCOMING <input checked="" type="checkbox"/> OUTGOING
ORGANIZATION Public Stakeholder				
SUBJECT Response to questions from November 1, 2005 Oyster Creek License Renewal Public Meeting				
SUMMARY (Continue on Page 2)				
BACKGROUND During a licensee renewal public meeting on November 1, 2005, a public stakeholder (Donald Warren) asked the NRC a question concerning an excessive cooldown that occurred in November 2000 (ref. NRC inspection report 05000219/2000-008, dated December 20, 2000). The Senior Resident Inspector (Marc S. Ferdas) committed to provide Mr. Warren a response to his question.				
CONVERSATION RECORD I contacted Mr. Warren at his home and discussed his question with him. I informed him that Oyster Creek has exceeded the technical specification requirement (cooldown rate of 100 degrees per hour) on 2 occasions, December 29, 1972 and November 15, 2000. I also informed Mr. Warren that Oyster Creek has NOT exceeded the technical specification bases fatigue limit assumption of 10 cooldowns of 300 degrees per hour.				
Mr. Warren asked additional questions concerning: <ol style="list-style-type: none"> 1. Where he could find information on the December 29, 1972 event; and 2. What inspections and/or testing has Oyster Creek performed on the drywell liner? 				
}SISP Review Complete: MSF (Reviewer's Initials) After declaring this document an Official Agency Record it will/will not be released to the Public.				
<i>Continue on Page 2</i>				
ACTION REQUIRED <ol style="list-style-type: none"> 1. Provide NRC reference which documents December 29, 1972 event. 2. Provide information concerning Oyster Creek drywell liner. 				
NAME OF PERSON DOCUMENTING CONVERSATION Marc S. Ferdas		SIGNATURE		DATE <div style="text-align: center;">11/17/2005</div>
ACTION TAKEN On November 17, 2005 at 12:30 pm Mr. Ferdas and Andrew Rosebrook (RI/DRP/Branch 7/Project Engineer) provided Mr Warren w/ the reference number to an NRC report which documents the 1972 event (Inspection Report 50-219/73-01, Accession Number 9604160473, Microfiche Address 88575/198-212). I also informed Mr. Warren that the NRC plans to review information related to the drywell liner during its license renewal inspection scheduled for 2006, and the review will be documented following the inspection.				
TITLE OF PERSON TAKING ACTION Senior Resident Inspector		SIGNATURE OF PERSON TAKING ACTION		DATE <div style="text-align: center;">11/17/2005</div>