

November 9, 2005

Mr. David A. Christian
Sr. Vice President and Chief Nuclear Officer
Dominion Resources
5000 Dominion Boulevard
Glenn Allen, VA 23060-6711

SUBJECT: ERRATA FOR MILLSTONE POWER STATION UNIT 2 AND UNIT 3 - NRC
INTEGRATED INSPECTION REPORT 05000336/2005004 AND
05000423/2005004

Dear Mr. Christian:

Please replace page A-2 of the Attachment: Supplemental Information, to the subject inspection report transmitted to you on November 7, 2005. The purpose of this change is to correct the items in the Section entitled "List of Items Opened, Closed and Discussed".

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response (if any) will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Should you have any questions concerning this change, we will be pleased to discuss them with you.

Sincerely,

/RA/

Paul G. Krohn, Chief
Projects Branch 6
Division of Reactor Projects

Docket Nos.: 50-336, 50-423
License Nos.: DPR-65, NPF-49

Enclosure: Page A-2 of Attachment entitled "Supplemental Information" to Inspection Report 05000336/2005004 and 05000423/2005004

cc w/encl:

J. A. Price, Site Vice President, Millstone Station
C. L. Funderburk, Director, Nuclear Licensing and Operations Support
D. W. Dodson, Supervisor, Station Licensing
L. M. Cuoco, Senior Counsel
C. Brinkman, Manager, Washington Nuclear Operations
J. Roy, Director of Operations, Massachusetts Municipal Wholesale Electric Company
First Selectmen, Town of Waterford
R. Rubinstein, Waterford Library
B. Sheehan, Co-Chair, NEAC
E. Woollacott, Co-Chair, NEAC
E. Wilds, Director, State of Connecticut SLO Designee
J. Buckingham, Department of Public Utility Control
G. Proios, Suffolk County Planning Dept.
R. Shadis, New England Coalition Staff
G. Winslow, Citizens Regulatory Commission (CRC)
S. Comley, We The People
D. Katz, Citizens Awareness Network (CAN)
R. Bassilakis, CAN
J. M. Block, Attorney, CAN
P. Eddy, Electric Division, Department of Public Service, State of New York
P. Smith, President, New York State Energy Research and Development Authority
J. Spath, SLO Designee, New York State Energy Research and Development Authority

Mr. D. A. Christian

3

Distribution w/encl (VIA E-MAIL):

S. Collins, RA
M. Dapas, DRA
S. Lee, RI OEDO
D. Roberts, NRR
V. Nerses, NRR
G. Wunder, NRR
R. Ennis, NRR
S. Schneider, Senior Resident Inspector
E. Bartels, Resident OA
P. Krohn, RI
S. Barber, RI
ROPreports@nrc.gov
Region I Docket Room (with concurrences)

SISP Review Complete: _____ BSN _____ (Reviewer's Initials)

DOCUMENT NAME: E:\Filenet\ML053420503.wpd

After declaring this document "An Official Agency Record" it ~~will/will not~~ be released to the Public.

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure

"E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RI/DRP		RI/DRP		
NAME	Norris/BSN		PKrohn/PGK		
DATE	11/08/05		11/09/05		

OFFICIAL RECORD COPY

NRC personnel

G. S. Barber, Senior Project Engineer, Division of Reactor Projects (DRP)
 J. C. Benjamin, Resident Inspector, DRP
 A. C. Cerne, Consultant, Division of Reactor Safety (DRS)
 L. S. Cheung, Senior Reactor Inspector, DRS
 J. M. D'Antonio, Operations Engineer, DRS
 G. X. Johnson, Reactor Inspector, DRS
 S. R. Kennedy, Resident Inspector, DRP
 G. J. Malone, Resident Inspector-Salem, DRP
 T. A. Moslak, Health Physicist, DRS
 S. M. Pindale, Senior Reactor Inspector, DRS
 S. M. Schneider, Senior Resident Inspector, DRP
 D. L. Werkheiser, Reactor Inspector, DRS

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSEDOpened and Closed

05000336/2005004-01	NCV	Failure to take TS action with the "B" EDG inoperable (1R14.2)
05000336,423/2005004-02	FIN	Failure to adequately implement operability determination procedure on three occasions (1R15)

Closed

05000336/2005-001-00	LER	Non Conformance With Surveillance Requirements (1R14.1)
05000336/2005-002-00	LER	Reactor Coolant System Pressure Boundary Leakage From Primary Water Stress Corrosion Cracking In A Pressurizer Heater Sleeve (4OA3)
05000336/2005-003-00, 01	LER	Non-Compliance With Technical Specifications Due to Installation Of Unqualified Test Equipment (1R14.2)
05000336/2004008-02	URI	Potential Inoperable Enclosure Air Conditioner (4OA5.1)
05000336/2005003-02	URI	Degradation of TDAFW Pump Cubicle HELB Protection Function (4OA5.2)