

(10-2003)
10 CFR 2.201

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

JANX Integrity
8500 E. Michigan Avenue
Parma, MI 49269

REPORT 2005 001

2. NRC/REGIONAL OFFICE

US NRC Reg III
2443 Wainnville Rd
Suite 210
Lisle, IL 60532

3. DOCKET NUMBER(S)

03011772

4. LICENSEE NUMBER(S)

21-16560-01

5. DATE(S) OF INSPECTION

December 1, 2005

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	G. Folk		12/1/05

**Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE JANX REPORT NUMBER(S) 2005-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-11772	4. LICENSE NUMBER(S) 21-16560-01	5. DATE(S) OF INSPECTION December 1, 2005	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01 - 03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT John Newland	4. TELEPHONE NUMBER 517/531-3911
Next Inspection Date: 12/06			
<input checked="" type="checkbox"/> Main Office Inspection			
<input checked="" type="checkbox"/> Field Office 2556 N. Sturgeon Rd, Midland, MI			
<input type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

The licensee is a radiographer located in Parma, Michigan with authorization to use material at authorized sites and at temporary job sites in the US where the NRC has jurisdiction. This licensee has six full time radiographers at the Parma facility and maintains ten 660B exposure devices at this location.

Performance Observations

At the time of the inspection, licensee was performing radiography on the premises of the Dow Chemical Co. Observation of the assigned radiographers was performed by the inspector. The inspector reviewed the paperwork associated with the use of the radiographic devices and interviewed personnel that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection.

Independent surveys around the storage facility yielded minimal results. Licensee personnel are badged. Readings for the past year were low and did not exceed 1500 mrem on average.

No violations of requirements were noted.