

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Professional Service Industries, Inc.
St. Paul, Minnesota2. NRC/REGIONAL OFFICE
U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road
Lisle, Illinois 60532-4352

REPORT 2006-001

3. DOCKET NUMBER(S)

030-11906

4. LICENSEE NUMBER(S)

12-16941-01

5. DATE(S) OF INSPECTION

2/21/06

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title

Printed Name

Signature

Date

LICENSEE'S
REPRESENTATIVE

NRC INSPECTOR

Michael M LaFranco

Michael M LaFranco

2/21/06

(10-2003)
10 CFR 2.201**Docket File Information**
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Professional Service Industries, Inc. REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-11906	4. LICENSE NUMBER(S) 12-16941-01	5. DATE(S) OF INSPECTION 2/21/2006	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01-03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 03121	2. PRIORITY K5	3. LICENSEE CONTACT John Thornton - CRSO	4. TELEPHONE NUMBER 630-691-1490
<input type="checkbox"/> Main Office Inspection <input checked="" type="checkbox"/> Field <u>St. Paul, Minnesota</u> <input type="checkbox"/> Temporary Job Site _____			
Next Inspection Date: <u>NA - Multiple sites listed</u>			

PROGRAM SCOPE

The licensee is authorized to possess and use Troxler, Campbell Pacific, Humboldt Scientific or Seaman Nuclear Corp. moisture/density gauges. The site inspected is one of many field facilities in the states of Michigan, Missouri, West Virginia, Pennsylvania, Virginia, Minnesota and Indiana. The licensee has a site radiation safety officer and two authorized users. However, no gauges have been used or stored from this facility since put on the license in 2005.

Performance Observations

The inspector verified that no gauges have been used at the facility by a review of records and interviews with licensee personnel. In interviews with licensee personnel, the inspector determined that the individuals had adequate knowledge to ensure the safe use and storage of licensed material. The licensee indicated that they plan on transferring gauges to the facility in the next several months.