

March 16, 2006

Mr. Michael R. Kansler
President
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

SUBJECT: INDIAN POINT NUCLEAR GENERATING UNIT NO. 2 - REQUEST FOR
ADDITIONAL INFORMATION REGARDING PROPOSED STEAM GENERATOR
EXAMINATION PROGRAM - 2006 REFUELING OUTAGE (2R17)
(TAC NO. MD0213)

Dear Mr. Kansler:

On February 13, 2006, Entergy Nuclear Operations, Inc. (Entergy), submitted the proposed steam generator examination program for 2006 refueling outage (2R17) in accordance with the requirements of Indian Point Nuclear Generating Unit No. 2 Technical Specifications 5.5.7.f.1.

The Nuclear Regulatory Commission staff is reviewing the submittal and has determined that additional information is needed to complete its review. The specific questions are found in the enclosed request for additional information (RAI). During a telephone call on March 14, 2006, the Entergy staff indicated that a response to the RAI would be provided within 30 days from the date of this letter.

Please contact me at (301) 415-2901 if you have any questions on this issue.

Sincerely,

/RA/

John P. Boska, Senior Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-247

Enclosure:
RAI

cc w/encl: See next page

March 16, 2006

Mr. Michael R. Kansler
President
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

SUBJECT: INDIAN POINT NUCLEAR GENERATING UNIT NO. 2 - REQUEST FOR
ADDITIONAL INFORMATION REGARDING PROPOSED STEAM GENERATOR
EXAMINATION PROGRAM - 2006 REFUELING OUTAGE (2R17)
(TAC NO. MD0213)

Dear Mr. Kansler:

On February 13, 2006, Entergy Nuclear Operations, Inc. (Entergy), submitted the proposed steam generator examination program for 2006 refueling outage (2R17) in accordance with the requirements of Indian Point Nuclear Generating Unit No. 2 Technical Specifications 5.5.7.f.1.

The Nuclear Regulatory Commission staff is reviewing the submittal and has determined that additional information is needed to complete its review. The specific questions are found in the enclosed request for additional information (RAI). During a telephone call on March 14, 2006, the Entergy staff indicated that a response to the RAI would be provided within 30 days from the date of this letter.

Please contact me at (301) 415-2901 if you have any questions on this issue.

Sincerely,

/RA/

John P. Boska, Senior Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-247

Enclosure:

RAI

cc w/encl: See next page

DISTRIBUTION:

PUBLIC	RidsNrrDorlLpla	RidsNrrPMJBoska	RidsOGCMailCenter
LPL1-1 Reading File	RidsNrrLASLittle	RidsAcrcAcnwMailCenter	
BSingal	ECobey, RI	YDiaz-Castillo	

ADAMS ACCESSION NUMBER: ML060740169

OFFICE	LPL1-1/PM	LPL1-1/LA	CSGB/BC	LPL1-1/BC
NAME	JBoska	SLittle	EMurphy for AHiser	RLaufer
DATE	3/15/06	3/16/06	3/16/06	3/16/06

OFFICIAL RECORD COPY

Indian Point Nuclear Generating Unit No. 2

cc:

Mr. Gary J. Taylor
Chief Executive Officer
Entergy Operations, Inc.
1340 Echelon Parkway
Jackson, MS 39213

Mr. John T. Herron
Senior Vice President and
Chief Operating Officer
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. Fred R. Dacimo
Site Vice President
Entergy Nuclear Operations, Inc.
Indian Point Energy Center
295 Broadway, Suite 1
P.O. Box 249
Buchanan, NY 10511-0249

Mr. Paul Rubin
General Manager, Plant Operations
Entergy Nuclear Operations, Inc.
Indian Point Energy Center
295 Broadway, Suite 2
P.O. Box 249
Buchanan, NY 10511-0249

Mr. Oscar Limpas
Vice President Engineering
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. Brian O'Grady
Vice President, Operations Support
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. John F. McCann
Director, Licensing
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Ms. Charlene D. Faison
Manager, Licensing
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. Michael J. Columb
Director of Oversight
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. James Comiotes
Director, Nuclear Safety Assurance
Entergy Nuclear Operations, Inc.
Indian Point Energy Center
295 Broadway, Suite 1
P.O. Box 249
Buchanan, NY 10511-0249

Mr. Patric Conroy
Manager, Licensing
Entergy Nuclear Operations, Inc.
Indian Point Energy Center
295 Broadway, Suite 1
P. O. Box 249
Buchanan, NY 10511-0249

Mr. Travis C. McCullough
Assistant General Counsel
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Ms. Stacey Lousteau
Treasury Department
Entergy Services, Inc.
639 Loyola Avenue
Mail Stop: L-ENT-15E
New Orleans, LA 70113

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Indian Point Nuclear Generating Unit No. 2

cc:

Senior Resident Inspector's Office
Indian Point 2
U. S. Nuclear Regulatory Commission
P.O. Box 59
Buchanan, NY 10511

Mr. Peter R. Smith, President
New York State Energy, Research, and
Development Authority
17 Columbia Circle
Albany, NY 12203-6399

Mr. Paul Eddy
Electric Division
New York State Department
of Public Service
3 Empire State Plaza, 10th Floor
Albany, NY 12223

Mr. Charles Donaldson, Esquire
Assistant Attorney General
New York Department of Law
120 Broadway
New York, NY 10271

Mayor, Village of Buchanan
236 Tate Avenue
Buchanan, NY 10511

Mr. Ray Albanese
Executive Chair
Four County Nuclear Safety Committee
Westchester County Fire Training Center
4 Dana Road
Valhalla, NY 10592

Mr. William DiProfio
PWR SRC Consultant
139 Depot Road
East Kingston, NH 03827

Mr. Daniel C. Poole
PWR SRC Consultant
P.O. Box 579
Inglis, FL 34449

Mr. William T. Russell
PWR SRC Consultant
400 Plantation Lane
Stevensville, MD 21666-3232

Mr. Jim Riccio
Greenpeace
702 H Street, NW
Suite 300
Washington, DC 20001

Mr. Phillip Musegaas
Riverkeeper, Inc.
828 South Broadway
Tarrytown, NY 10591

Mr. Mark Jacobs
IPSEC
46 Highland Drive
Garrison, NY 10524

REQUEST FOR ADDITIONAL INFORMATION
REGARDING PROPOSED STEAM GENERATOR INSPECTION PROGRAM
2006 REFUELING OUTAGE (2R17)
ENTERGY NUCLEAR OPERATIONS, INC.
INDIAN POINT NUCLEAR GENERATING UNIT NO. 2
DOCKET NO. 50-247

In a letter dated February 13, 2006, Agencywide Documents Access and Management System Accession No. ML060530378, Entergy Nuclear Operations, Inc. (Entergy) submitted its proposed steam generator examination program for the spring 2006 refueling outage for Indian Point Nuclear Generating Unit No. 2 in accordance with Technical Specification 5.5.7.f.1. The Nuclear Regulatory Commission (NRC) staff is reviewing the submittal and has the following questions:

1. A couple of plants with thermally treated Alloy 600 steam generator tubes have identified crack-like indications in the portion of the tube within the tubesheet region (refer to Information Notice 2005-09, "Indications in Thermally Treated Alloy 600 Steam Generator Tubes and Tube-to-Tubesheet Welds)." These crack-like indications occurred prior to observing cracking at any other location (e.g., expansion transition, U-bend). Please discuss your basis for not performing any rotating probe inspections near the tube-to-tubesheet weld, tack expansion, or overexpansions (bulges or tubesheet anomalies).
2. The NRC staff notes that as part of your proposed Steam Generator Examination Program for your 2006 refueling outage (2R17), no plans were identified to inspect dings or dents with a rotating probe. Depending on their size, dings and dents may not be readily inspected with a bobbin probe. In addition, circumferential cracking that could occur at dents and dings will generally not be detectable with a bobbin probe. Dings and dents can increase the stress levels in the tube making them an area more susceptible to cracking than other portions of the tube. As a result, please provide your basis for not inspecting dings or dents with a rotating probe.

Enclosure