


Plant Engineering Branch Open Items Interim Safety Basis							
SITE	ACT ORG	PEB LEAD	Item	Type	Issue	Planned Closure Quarter Interim Safety Basis	Disposition/Status/URI for Significance
CGS	NRR	RPM	AV 2003 002- 01	Associated Circuits	Failure to ensure that one train of low pressure coolant injection was free of fire damage. Two multiple spurious actuators (hot shorts) for two valves in series could result in a flow diversion.	CY 2005 Quarter 4 Comp measures established	Waiting on generic resolution of associated circuits. Unresolved for compliance in IR 2003-02 dated June 2, 2003. 
CWY	NRR	NFO	URI 2003 007- 01	Associated Circuits	Failure to protect associated circuits from fire damage or provide diverse means to achieve safe shutdown	CY 2005 Quarter 4 Licensee has changed fire pre-plans to include the identified components as being subject to possible fire-induced mal- operation.	Waiting on associated circuits generic resolution. Unresolved for significance and compliance in IR 2003-007 dated 11/28/2003 <u>R:\2003\CW2003-007-nfo.wpd</u>

Information in this record was deleted
in accordance with the Freedom of Information
Act, exemptions 5
FOIA- 2006-0095