



RECEIVED  
REGION 1

2006 MAR 17 AM 11:14

NMSB1

Licensing Branch  
Nuclear Materials Safety Section  
Division of Safety & Safeguards  
U.S. N.R.C. - Region I  
475 Allendale Rd.  
King of Prussia, PA 19406

March 10, 2006

Dear License Reviewer,

03003018

Please amend our Byproduct Materials License (# 37-02385-02) to reflect the following changes in our program:

Remove as a location of use the 234 Parker Street, Carlisle, Pa. address as our entire operation is now located at 45 Sprint Drive, Carlisle, PA.

All sealed sources are now stored at 45 Sprint Drive location.

Enclosed is the closeout survey of the Parker Street facility.

If you have any questions, please contact our consultant radiation physicist and radiation safety officer, Jack Olley, of Walter L. Robinson and Associates at 717-291-9813 voice mail box 3.

Sincerely,

A handwritten signature in black ink, appearing to read 'William H. Leonard'.

William H. Leonard  
Chief Executive Officer

Enclosure

138591

NMSS/RONI MATERIALS-002



**NRC License # 37-02385-02**

**Close out survey on the 246 Parker Street Address**

**Date: March 1, 2006**

**SURVEY RESULTS**

**Background: 0.05 mR/hr**  
**Hot Lab: 0.04 mR/hr**  
**Imaging areas (maximum reading): 0.04 mR/hr**  
**Treadmill area: 0.05 mR/hr**  
**Injection area: 0.05 mR/hr**  
**Uptake/well area: 0.05 mR/hr**


**Survey measured with Ludlum 14 C meter**

**WIPE RESULTS**

**Treadmill: 430 dpm**  
**Imaging areas (maximum reading) 420 dpm**  
**Hot Lab: 440 dpm**  
**Injection area: 430 dpm**  
**Uptake/well area: 430 dpm**

**Wipes performed on Atom Lab 950 well counter**

**All areas may be released as unrestricted areas.**

  
\_\_\_\_\_  
**Jack A. Olley**  
**Radiation Safety Officer**

This is to acknowledge the receipt of your letter/application dated

3/10/2006, and to inform you that the initial processing which includes an administrative review has been performed.

☒ AMEND. 32-02385-02  
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

☐ Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 138591.  
When calling to inquire about this action, please refer to this control number.  
You may call us on (610) 337-5398, or 337-5260.