

March 31, 2006

MEMORANDUM TO: Russell A. Gibbs, Chief
Reactor Inspection Branch
Division of Inspection and Regional Support
Office of Nuclear Reactor Regulation

FROM: */RA/*
Neil F. O'Keefe, Acting Chief
Operator Licensing and Human Performance Branch
Division of Inspection and Regional Support
Office of Nuclear Reactor Regulation

SUBJECT: INSPECTION PROCEDURE 41301, PRE-LICENSING REVIEW OF
TRAINING AND QUALIFICATION PROGRAMS (TAC MC9386)

The Operator Licensing and Human Performance Branch (IOLB) has been assigned responsibility for revising and/or updating Inspection Procedure 41301, Pre-licensing Review of Training and Qualification Programs (IP41301).

A review of IP41301 has shown that it will be possible to incorporate all inspection requirements contained in IP41301 into Inspection Procedure 41500, Training and Qualification Effectiveness (IP41500).

As a result, it is IOLB's intention to close TAC 9386 and incorporate the inspection requirements of IP41301 into IP41500. In addition, IOLB recommends that IP41301 be cancelled.

If you have any questions, contact either myself at 415-1676 or Rick Pelton, of my staff, at 425-1028.

March 31, 2006

MEMORANDUM TO: Russell A. Gibbs, Chief
Reactor Inspection Branch
Division of Inspection and Regional Support
Office of Nuclear Reactor Regulation

FROM: */RA/*
Neil F. O'Keefe, Acting Chief
Operator Licensing and Human Performance Branch
Division of Inspection and Regional Support
Office of Nuclear Reactor Regulation

SUBJECT: INSPECTION PROCEDURE 41301, PRE-LICENSING
REVIEW OF TRAINING AND QUALIFICATION PROGRAMS
(TAC MC9386)

The Operator Licensing and Human Performance Branch (IOLB) has been assigned responsibility for revising and/or updating Inspection Procedure 41301, Pre-licensing Review of Training and Qualification Programs (IP41301).

A review of IP41301 has shown that it will be possible to incorporate all inspection requirements contained in IP41301 into Inspection Procedure 41500, Training and Qualification Effectiveness (IP41500).

As a result, it is IOLB's intention to close TAC 9386 and incorporate the inspection requirements of IP41301 into IP41500. In addition, IOLB recommends that IP41301 be cancelled.

If you have any questions, contact either myself at 415-1676 or Rick Pelton, of my staff, at 425-1028.

Distribution:

IROB RF
MAAshley

ADAMS Accession No.: ML060890191

OFFICE	IOLB/DIRS	IOLB/DIRS
NAME	R Pelton	N. O'Keefe
DATE	03 /30/06	03/31/06

OFFICIAL RECORD COPY