

EXPERT SYSTEM LICENSE EVALUATION  
EVALUATION REPORT FOR LICENSE 19-08654-01

Licensee: DEPARTMENT OF THE TREASURY      CUSTOMS LAB  
Site of operation: 103 GAY STREET, BALTIMORE, MD

--Type and form of materials licensed--  
Material--      --Form--  
SR-90      Sealed  
XE-133      Sealed

---

--For evaluation purposes, amounts of the following materials were obtained--  
Material--      --Form--      --Amount--      --Unit--  
SR-90      SEALED      .060      CI

Initial rank for the SEALED sources is:      0.52

1. License included only sealed sources
2. There was at least one sealed source authorized on this license which was not accounted for by the disposition information.
3. Sealed sources/shielding on the license were of low to moderate hazard.

---

Category for sealed sources: No criteria to eliminate license-sources not haz

---

The final ranking for SEALED SOURCES is BELOW 1

---

Reviewer's comments concerning license 19-08654-01

---

THERE IS A NOTE IN THIS FILE DATED 7/10/73 STATING NO MATERIAL ON HAND AND THAT THERE IS NO NEED TO RENEW THE LICENSE. NOTICE WAS TO BE SENT TO CLOSE OUT. HOWEVER THE FILE CONTAINED NO DISPOSITION DATA. FROM INFORMATION ON THE APPLICATION FOR LICENSE THE LICENSEE COULD POSSESS SEALED SOURCES OF STRONTIUM-90, (ACTIVITY NOT TO EXCEED 20 MILLICURES PER SOURCE) NOT TO EXCEED 3 IN NUMBER. BASED ON THIS IT WAS ASSUMED THAT THE LICENSEE POSSESSED 3 SEALED SOURCES OF SR-90.

---

EXPERT SYSTEM EVALUATION WAS BASED ON THE  
INVENTORY RECORD IN JOB 0338, BOX 41

Docket 30-04546

Licensee: DEPARTMENT OF THE TREASURY      CUSTOMS LAB  
Address: BALTIMORE, MD      Zip: 21202  
State of operation: MD  
Site used: 103 GAY STREET, BALTIMORE, MD  
Disposition information present: NO DISPOSITION INFORMATION GIVEN  
This license was listed as expired on 07/31/73  
Remarks: NOTE 7/10/73: NO MATL ON HAND- NO NEED FOR RENEWAL OF LICENSE  
JOB NUMBER: 0338      BOX NUMBER: 41

---

Date of last evaluation/revision: 01/27/93

Reviewer: BWK