

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Bristol-Myers Squibb Medical Imaging
331 Treble Cove Road
North Billerica, MA 01862 (Maryland Hts, MO site)

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road
Lisle, Illinois 60532-4351

REPORT

2006-001

3. DOCKET NUMBER(S)

030-13288

4. LICENSEE NUMBER(S)

20-00320-19

5. DATE(S) OF INSPECTION

July 13, 2006

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title

Printed Name

Signature

Date

LICENSEE'S
REPRESENTATIVE

NRC INSPECTOR

Deborah A. Piskura



7/13/2006

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE Bristol-Myers Squibb Medical Imaging REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-13288	4. LICENSE NUMBER(S) 20-00320-19	5. DATE(S) OF INSPECTION July 13, 2006	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01, 03.02, 03.03, 03.04, 03.05, 03.06, and 03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM 03214	2. PRIORITY E 5	3. LICENSEE CONTACT Donald Chartrand, RSO	4. TELEPHONE NUMBER 978.671.8333
<div style="display: flex; justify-content: space-between;"><div><input type="checkbox"/> Main Office Inspection</div><div>Next Inspection Date: <u>July 2011</u></div></div> <div style="display: flex; justify-content: space-between;"><div><input checked="" type="checkbox"/> Field Office <u>2684 Metro Blvd. Maryland Heights, MO</u></div><div></div></div> <div style="display: flex; justify-content: space-between;"><div><input type="checkbox"/> Temporary Job Site</div><div></div></div>			

PROGRAM SCOPE

This small distribution center of BMS (one of 4 in the U.S.) maintained a small inventory of radiopharmaceuticals (Mo-99/Tc-99m generators, Xe-133, Sm-153 and P-32) at its Maryland Heights center. The facility maintained its inventory of materials to support customer needs in the Midwest. This facility did not process or manipulate RAM; the facility re-packaged RAM for distribution purposes only. An individual, working under contract through Associated Couriers, managed the day-to-day operations.

This inspection consisted of a tour of the lab and the radioactive material storage areas; review of selected records; interviews with licensee staff, and independent area surveys. The inspector observed licensee personnel perform inventories, package receipt surveys, opening packages and preparing packages for short-term storage within the storage areas. The inspector also observed the licensee's security of RAM and its use of personnel monitoring. The licensee informed the inspector that this facility expected to cease operations and would be closing in August 2006. The inspector discussed the licensee termination process with the site personnel and the corporate RSO.