

Dominion Nuclear Connecticut, Inc.
Millstone Power Station
Rope Ferry Road
Waterford, CT 06385



Dominion™

JUL 7 2006

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

Serial No.	06-546
MPS Lic/WDB	R0
Docket No.	50-423
License No.	NPF-49

DOMINION NUCLEAR CONNECTICUT, INC.
MILLSTONE POWER STATION UNIT 3
CANCELLATION OF LICENSEE EVENT REPORT 2004-003-00

On January 3, 2005, Dominion Nuclear Connecticut, Inc., (DNC) submitted Licensee Event Report (LER) MP3-2004-003 pursuant to 10 CFR 50.73(a)(2)(i)(B) and 10 CFR 50.73(a)(2)(v)(B). This LER documented two conditions at Millstone Power Station Unit 3 (MPS 3), in which the High Pressure Safety Injection (HPSI) system, a component of the Emergency Core Cooling system (ECCS) subsystem listed in MPS 3 Technical Specification 3.5.2, previously evaluated as operable, may have been inoperable. Subsequent to the submittal of the LER, a technical evaluation was completed that concluded that while the HPSI system was degraded, the ECCS subsystem remained operable in the as found condition. Therefore, DNC is formally withdrawing LER MP3-2004-003.

If you have any questions or require additional information, please contact Mr. David W. Dodson at (860) 447-1791, extension 2346.

Very truly yours,


J. Alan Price
Site Vice President - Millstone

IE22

Attachments: None

Commitments made in this letter: None.

cc: U.S. Nuclear Regulatory Commission
Region I Regional Administrator
475 Allendale Road
King of Prussia, PA 19406-1415

Mr. V. Nerses
NRC Senior Project Manager Millstone Units 2 and 3
U.S. Nuclear Regulatory Commission, Mail Stop 8 C2
One White Flint North
11555 Rockville Pike
Rockville, MD 20852-2738

Mr. S. M. Schneider
NRC Senior Resident Inspector
Millstone Power Station