

NRC FORM 591M PART 1
(10-2003)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Sadat Associates, Inc.
335 ~~N. 15th~~ 1545 LAMBERTON RD.
Monmouth Junction, NJ 08852
TRENTON, NJ 08610

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region I, 475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

REPORT Nos. 2006-001

3. DOCKET NUMBER(S)

03035666

4. LICENSE NUMBER(S)

29-30252-02

5. DATE(S) OF INSPECTION

July 27, 2006

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☒ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1800, to exercise discretion, were satisfied.
- ☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

Licensee committed to correct violations listed below within 30 days, i.e. file amendment request for new location of use & new gauge provide HMMAT training & perform audit per 2005.

- ☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

- (1) Licensee failed to file an Application for Amendment before moving gauge to new location & changing Radiation Safety Officer as required by License Condition 18.21 committing to Application dated 2-6-2001.
- (2) Licensee failed to provide HMMAT training to gauge users as required by 10 CFR 71.5 + 49 CFR 172.704(c)(2).
- (3) Licensee failed to perform annual audits of rad-safety program for 2002-2005. AS required by 10 CFR 20.1101(c)(4).

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	JOSEPH B WILBY III	<i>Joseph B Wilby</i>	8/1/06
NRC INSPECTOR	Michelle Beardsley	<i>Michelle Beardsley</i>	7-31-06

NRC FORM 591M PART 1 (Rev. by R) 07/05)

G:\Docs\Current\Inep Record\R29-30252-02.2006-001.591P1.wpd

SUNSI Review Completed By:

/RA/

M Beardsley

☒ Public☒ Non-Sensitive