

R2/857

One Liners for 5/30/02

Westinghouse

All lines are functioning smoothly. Only 1 conversion line is left to be upgraded for the PLC correction, which is on schedule to be completed before the July 31st deadline.

One unusual event occurred at the facility. A fitting on the UNH tanks began leaking and spilled approximately 10 gallons of solution on the dike floor. The spill has since then been cleaned up and the fitting repaired.

Five workers were put on restriction when an air sampler for their area came in high. It is believed the sampler was contaminated when it was knocked to the floor. However, the employees will continue to be on restriction until bio assays determine otherwise.

7/1-20