

R2/E22

Westinghouse Highlights

Events (9101 and other issues) 1/9/00 - 12/29/01	2/00 - Spill of uranyl nitrate material in the UF6 Bay. 7/00 - Violation of Shipping Container Certificate of Compliance USA/9203/AF. 7/00 - Deficiency in the procedure review and approval process for "Filter Disassembly Process". 10/00 - Blockage by debris compromised the Condensate Level Detector in a vaporizer. 12/00 - Shipment of three containers with excessive contact levels.		
Occupational Exposure	1998 1999 2000 2001 (est.)	<u>Collective Dose</u> 222 person-rem 305 person-rem 554 person-rem 880 person-rem	<u>Maximum TEDE</u> 2.73 rem 3.04 rem 4.18 rem 4.10 rem
Radioactive Liquid and Gaseous Effluent Releases	1998 1999 2000 2001 (est.)	U U U U <u>Liquid (mCi)</u> 42.0 51.0 124.0 32.0	<u>Gaseous (μCi)</u> 464 453 501 335
Maximum Offsite Dose due to Gaseous Releases	1998 1999 2000 2001 (est.)	< 1 mrem < 1 mrem < 1 mrem < 1 mrem	
Labor/Union Issues	None		
Major Management Changes	4/01 - S. McDonald appointed Manager, Regulatory Affairs replacing D. Goldbach		

Ex. 4

G:\ASSESS\LICENSEE\WEST\LPR 2002\Westinghouse Highlights.wpd

Information in this record was deleted
 in accordance with the Freedom of Information
 Act, exemptions 4
 FOIA-2006-0026

K-8