

REGION IV MATERIALS LICENSEE EVENT REPORT SUMMARY - AUGUST 2006

October 25, 2006

Region IV Table 1 DNMS LICENSEE EVENT REPORTS--OPENED AUGUST 2006							
REPORT DATE	EVENT DATE	DATE REC'D	LICENSEE	LICENSE NUMBER	REPORTING REQUIREMENT	DESCRIPTION	STATUS
06/17/06	06/17/06	06/17/06 ★	Halliburton Energy Services	42-01068-07	10 CFR 39.77(c) and (d)	Irretrievable well logging source Gulf of Mexico	Closed
04/11/06	03/08/06	04/17/06 ★	Kakivik Asset Management, LLC	50-27667-01	30.50(b)(2) & 34.101(a)(1)	Failure of safety equipment - radiography source disconnect during routine operations	Closed
07/20/06	07/20/06	07/20/06 ☼	Halliburton Energy Services	42-01068-07	10 CFR 39.77(c) and (d)	Irretrievable well logging source Gulf of Mexico	Closed
08/10/06	08/10/06	08/11/06	Southern California Edison SONGS, Unit 1	DRP-13	N/A Voluntary Notification	Licensed Material detected in groundwater	Open
08/15/06	07/13/06	08/21/06	University of Hawaii at Manoa	53-00017-23	10 CFR 20.2201(a)(ii)	Loss of licensed material	Closed
08/26/06	08/26/06	08/28/06	Halliburton Energy Services	42-01068-07	10 CFR 39.77(c) and (d)	Irretrievable well logging source Gulf of Mexico	Open

★ Event inadvertently left off reports for June and July 2006.

★ Event report not set up in DNMS LER System until August 15, 2006.

☼ Event left off report for July 2006.

<b>Region IV    Table 2</b> <b>DNMS LICENSEE EVENT REPORTS</b> <b>Previously Received and Still Under Review</b> <b>Current for AUGUST 2006</b>							
<b>REPORT DATE</b>	<b>EVENT DATE</b>	<b>DATE REC'D</b>	<b>LICENSEE</b>	<b>LICENSE NUMBER</b>	<b>REPORTING REQUIREMENT</b>	<b>DESCRIPTION</b>	<b>STATUS</b>
07/14/05	07/14/05	07/15/05	Global X-Ray & Testing Corporation	LA-0577-L01❖	10 CFR 34.101(a)(2)	During radiographic operations on pipe lay barge, a source assembly did not retract to its fully shielded and secure position. RSO was dispatched to the remote site and recovered the source.	Open
05/05/06	05/05/06	05/05/06	Precision Energy Systems	42-26891-01	10 CFR 39.77(c) and (d)	Irretrievable well logging source Offshore Louisiana, Gulf of Mexico.	Open
05/10/06	05/09/06	05/15/06	Bozeman Deaconess Foundation dba Bozeman Deaconess Hospital	25-10994-04	10 CFR 35.3045(a)(3)	Medical Event - dose to unintended site	Open
06/23/06	06/23/06	06/23/06	Department of the US Air Force	42-23539-01AF	10 CFR 2201.(a)(1)(i)	Inventory indicates loss of 2 detector sources at AFB	Open
07/07/06	06/25/06	07/07/06	Schlumberger Technology Corporation	42-00090-03	10 CFR 39.77(c) and (d)	Irretrievable well logging source Campbell Co, WY	Open
07/31/06	07/09/06	08/01/06	Acuren Inspection, Inc.	42-27593-01	10 CFR 20.50(b)(2)	Safety equipment failure - radiography guide tube crimped by object falling on it	Open

❖ Agreement State Licensee working under the reciprocity provisions of 10 CFR 150.20.

Region IV Table 3 DNMS LICENSEE EVENT REPORTS--CLOSED AUGUST 2006 (See attached Licensee Event Report Evaluation Form)							
REPORT DATE	EVENT DATE	DATE REC'D	LICENSEE	LICENSE NUMBER	REPORTING REQUIREMENT	DESCRIPTION	STATUS
04/29/06	04/29/06	05/01/06	Weatherford US, LP	LA- 4466-L01 ❖	10 CFR 39.77(c) and (d)	Irretrievable well logging source Offshore Louisiana, Gulf of Mexico.	Closed
06/28/06	06/28/06	06/28/06	Schlumberger Technology Corporation	42-00090-03	10 CFR 39.77(c) and (d)	Irretrievable well logging source Offshore Gulf of Mexico.	Closed
07/05/06	07/04/06	07/05/06	Schlumberger Technology Corporation	42-00090-03	10 CFR 39.77(c) and (d)	Irretrievable well logging source Offshore Gulf of Mexico.	Closed
06/17/06	06/17/06	06/17/06 ★	Halliburton Energy Services	42-01068-07	10 CFR 39.77(c) and (d)	Irretrievable well logging source Gulf of Mexico	Closed
04/11/06	03/08/06	04/17/06 ★	Kakivik Asset Management, LLC	50-27667-01	30.50(b)(2) & 34.101(a)(1)	Failure of safety equipment - radiography source disconnect during routine operations	Closed
07/20/06	07/20/06	07/20/06 ☼	Halliburton Energy Services	42-01068-07	10 CFR 39.77(c) and (d)	Irretrievable well logging source Gulf of Mexico	Closed
08/15/06	07/13/06	08/21/06	University of Hawaii at Manoa	53-00017-23	10 CFR 20.2201(a)(ii)	Loss of licensed material	Closed

★ Event inadvertently left off reports for June and July 2006.

★ Event report not set up in DNMS LER System until August 15, 2006.

☼ Event left off report for July 2006.

❖ Agreement State Licensee working under the reciprocity provisions of 10 CFR 150.20.

