

REGION IV MATERIALS LICENSEE EVENT REPORT SUMMARY - SEPTEMBER 2006

October 25, 2006

Region IV Table 1 DNMS LICENSEE EVENT REPORTS--OPENED SEPTEMBER 2006							
REPORT DATE	EVENT DATE	DATE REC'D	LICENSEE	LICENSE NUMBER	REPORTING REQUIREMENT	DESCRIPTION	STATUS
09/14/06	09/14/06	09/14/06	Department of the US Air Force	42-23539-01AF	10 CFR 2201.(a)(1)(i)	Inventory indicates loss of 2 navigation system sources at AFB	Open
09/29/06	04/24/06	09/29/06	FMRI, Inc.	SMB-911	10 CFR 2203(a)(3)(ii)	Collection samples taken in September and October 2006 indicate concentration of licensed material exceeding a regulatory limit.	Open

Region IV Table 2 DNMS LICENSEE EVENT REPORTS Previously Received and Still Under Review Current for SEPTEMBER 2006							
REPORT DATE	EVENT DATE	DATE REC'D	LICENSEE	LICENSE NUMBER	REPORTING REQUIREMENT	DESCRIPTION	STATUS
07/14/05	07/14/05	07/15/05	Global X-Ray & Testing Corporation	LA-0577-L01❖	10 CFR 34.101(a)(2)	During radiographic operations on pipe lay barge, a source assembly did not retract to its fully shielded and secure position. RSO was dispatched to the remote site and recovered the source.	Open
05/10/06	05/09/06	05/15/06	Bozeman Deaconess Foundation dba Bozeman Deaconess Hospital	25-10994-04	10 CFR 35.3045(a)(3)	Medical Event - dose to unintended site	Open
07/07/06	06/25/06	07/07/06	Schlumberger Technology Corporation	42-00090-03	10 CFR 39.77(c) and (d)	Irretrievable well logging source Campbell Co, WY	Open
07/31/06	07/09/06	08/01/06	Acuren Inspection, Inc.	42-27593-01	10 CFR 20.50(b)(2)	Safety equipment failure - radiography guide tube crimped by object falling on it	Open

❖ Agreement State Licensee working under the reciprocity provisions of 10 CFR 150.20.

★ Event inadvertently left off reports for June and July 2006.

Region IV Table 3 DNMS LICENSEE EVENT REPORTS–CLOSED SEPTEMBER 2006 (See attached Licensee Event Report Evaluation Form)							
REPORT DATE	EVENT DATE	DATE REC'D	LICENSEE	LICENSE NUMBER	REPORTING REQUIREMENT	DESCRIPTION	STATUS
05/05/06	05/05/06	05/05/06	Precision Energy Systems	42-26891-01	10 CFR 39.77(c) and (d)	Irretrievable well logging source Offshore Louisiana, Gulf of Mexico.	Closed
06/23/06	06/23/06	06/23/06	Department of the US Air Force	42-23539-01AF	10 CFR 2201.(a)(1)(i)	Inventory indicates loss of 2 detector sources at AFB	Closed
08/10/06	08/10/06	08/11/06	Southern California Edison SONGS, Unit 1	DRP-13	N/A Voluntary Notification	Licensed Material detected in groundwater	Closed

SUNSI Review Completed: YES ADAMS: ☒ Yes ☐ No Initials: MCM

☒ Publicly Available ☐ Non-Publicly Available ☐ Sensitive ☒ Non-Sensitive

DOCUMENT NAME: s:\dnms\mmb\LERs\2006\09 Sept LER tables.wpd

RIV:DNMS:NMIB	C:NMIB
MCMaier	VHCampbell
/RA/	/RA/
10/25/06	10/26/06