



**Hanson Aggregates  
Northeast Region**

P.O. Box 231  
Easton, PA 18044-0231  
Tel + 610 253 4271  
Fax + 610 253 5734

October 30, 2006

U.S Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Reply to A Notice of Violation EA-06-219  
License No. 37-18463-01

To Whom It May Concern:

Please accept this correspondence as Hanson Aggregates Inc's Reply to a Notice of Violation EA-06-219.

If you have any questions, suggestions or comments please call us at 610-253-4271, Ext 273.

Sincerely,

Richard Hermany  
Radiation Safety Officer

CC: Regional Administrator, Region I  
Dennis M. Dolan, President & COO  
Mark Kendrick, Vice President  
John Sprague, Construction Manager

IED 7

## Reply to a Notice of Violation EA-06-219

Hanson Aggregates Pennsylvania, Inc.  
Easton, PA

Docket No. 03015128  
License No. 37-18463-01

### Violation A

- 1) The portable gauge was being temporarily stored in a sea van storage container. The permanent storage area no longer exists due to a fire that destroyed the entire office and storage complex.
- 2) Two locks have been installed on the sea van storage container doors, providing two physical barriers.
- 3) When the office and storage building are rebuilt, a permanent location with two physical barriers will be provided.
- 4) This condition was corrected on August 16, 2006.

### Violation B

- 1) The individual who used the gauge previously forgot to install the lock in the source handle. The lock on the outside of the case was engaged according to gauge user Henry McCormick.
- 2) Obtained the source handle lock from the previous user and reinstalled both locks.
- 3) Reviewed locking procedure with gauge users. Ensure gauge is locked properly when not in use. Review locking procedures when conducting 6 month internal audit.
- 4) This condition was corrected on August 16, 2006.

### Violation C

- 1) This was an oversight on behalf of Hanson employees and Troxler Electronic Laboratories.
- 2) The Bill of Lading and the Transportation guide have been revised. Corrected copies are with the gauge at all times.
- 3) All required documentation will be reviewed when internal audits are conducted. The necessary corrections will be made in a timely manner.
- 4) This condition was corrected on August 17, 2006.