

IEB:REB (LIC 47-260-2)

Oak Ridge, Tennessee  
August 26, 1957

Carbide & Carbon Chemicals Company  
Special Instrumentation Department  
Instrument Division  
South Charleston 3, West Virginia

Attn: Mr. L. J. Rogers

Dear Mr. Rogers:

The report of the inspection made on May 23, 1957, of the facilities, equipment and procedures related to your activities licensed under AEC Byproduct Material License Number 47-260-2 has been received and reviewed by the Commission.

The report indicates a deficiency in your operations with regard to the provisions of "Licensing of Byproduct Material," contained in Title 10, Code of Federal Regulations, Part 30, as follows:

1. Section 30.3 in that 200 millicuries of Cobalt 60 in your possession was not licensed.

The report indicates a deficiency in your operations with regard to the provisions of "Standards for Protection Against Radiation" contained in Title 10, Code of Federal Regulations, Part 20, as published in the Federal Register, January 29, 1957.

2. Section 20.203 in that areas with radiation levels exceeding 5 mr/hr were not posted with the required radiation caution signs.

The report further indicates that adjustments would be made in your program in conformance with these regulations. It is requested that you inform this office within 30 days as to the action you have taken or intend to take. These adjustments will be reviewed during the next inspection of your facilities.

Very truly yours,

bcc: Dr. Paul C. Aebersold  
DCA, Washington, D. C.

bcc: Mr. Leo Dubinski  
Inspection Div., ORO  
Isotopes

G. W. Morgan, Chief  
Isotopes Extension  
Division of Civilian Application

Brinkman/hm

8/26/57

A-4