



Radiological Physics Service, Inc.

3839 Napier Road
Plymouth, MI 48170
(734) 455-4780
Fax: (734) 453-8851

August 9, 2007

Fax to: Loren Heuter
Fax Number: 630-515-1078

From: Vincent McCormick, M.S.
Radiological Physics Service, Inc.
(734)395-9323
Fax: (248) 853-6547

Mr. Heuter,

You should have received the response to your fax to me from Dr. Elian. I am sending the results of the close-out survey and the most recent sealed source inventory and leak test. He has the signed copy of these.

I will be doing their quarterly inspection next week, including a leak test of the sealed sources.

If you have any questions, give me a call.

I will call you tomorrow to make sure you received everything you needed.

Thanks,
Vince

PHYSICISTS:

MICHIGAN

Ray A. Carlson, M.S.
Cell: (734) 395-7361
rcarlson@voyager.net

Laura T. Smith, M.S.
Cell: (586) 215-5947
LSphysics@comcast.net

Vincent McCormick, M.S.
Cell: (734) 395-9323
V_mccormick@comcast.net

Joshua D. Hack, B.S.
Cell: (734) 645-9991
Joshua.hack@utoledo.edu

SOUTH CAROLINA


Dan L. Marx, M.S.
Cell: (810) 730-6004
dmarx@voyager.net

GEORGIA

Diane Griffiths, M.S.
Cell: (770) 355-7709
dianegriffiths@comcast.net

MONTANA/CALIFORNIA

Bruce Austin, PhD
Cell: (909) 273-4613
baustin1@earthlink.net



CLOSE-OUT SURVEY
Flint Cardiovascular Consultants
G-3286 Beecher Road
Flint, MI

NRC License # 21-32550-01

Area #	Location	Survey (mR/h)	Wipe (dpm)
1	Hot Lab Floor (Right)	0.03	24
2	Hot Lab Floor (Left)	0.03	10
3	Floor (Stress Lab)	0.03	0
4	Floor (Stress Lab)	0.03	0
5	Floor (Stress Lab)	0.03	0
6	Floor (Stress Lab)	0.03	18
7	Floor (Stress Lab)	0.03	0
8	Floor (Stress Lab)	0.03	0
9	Floor (Stress Lab)	0.03	22
10	Floor (Stress Lab)	0.03	0
11	Floor (Imaging Room)	0.03	0
12	Floor (Imaging Room)	0.03	0
13	Floor (Imaging Room)	0.03	71
14	Floor (Imaging Room)	0.03	0
15	Floor (Imaging Room)	0.03	0
16	Floor (Imaging Room)	0.03	0
17	Floor (Imaging Room)	0.03	36
18	Floor (Imaging Room)	0.03	0
19	Floor (Imaging Room)	0.03	24
20	Floor (Imaging Room)	0.03	0
21	Floor (Imaging Room)	0.03	0
22	Floor (Imaging Room)	0.03	0
23	Floor (Imaging Room)	0.03	0
24	Floor (Imaging Room)	0.03	0

Location: Flint Cardiovascular Consultants

Date of Inspection: June 25, 2007

SEALED SOURCE INVENTORY

NUCLIDE	TYPE	LOCATION	CALIBRATION		DATE	MFGR	M/N	S/N
			ACTIVITY					
Cs-137	Vial	Hot Lab	198.4	uCi	1/10/2005	IPL		1093-1-15
Ba-133	Vial	Hot Lab	266.5	uCi	1/1/2005	IPL		1074-83-8
Cs-137	Rod	Hot Lab	0.5	uCi	11/1/2004	IPL		1034-49-91
Cs-137	Button	Survey Meter	1	uCi	10/1/2004	Spectrum		2951
Cs-137	Button	Survey Meter	1	uCi	10/1/2004	Spectrum		2743

RSO: _____

SEALED SOURCE LEAK TEST

NUCLIDE	TYPE	LOCATION	CALIBRATION		DATE	MFGR	M/N	S/N
			ACTIVITY					
Cs-137	Vial	Hot Lab	198.4	uCi	1/10/2005	IPL		1093-1-15
Ba-133	Vial	Hot Lab	266.5	uCi	1/1/2005	IPL		1074-83-8

COMMENT: The sources listed above were leak tested using a wipe technique and were found to have less than 0.005 uCi removable activity.

TESTED BY: Vincent McCormick, M.S.

DATE: June 25, 2007

RSO: _____

Nuclear License Number: 21-32550-01