

MAY 05 2010

LES-10-00089-NRC

Attn: Document Control Desk  
Director  
Office of Nuclear Material Safety and Safeguards  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

Louisiana Energy Services, LLC  
NRC Docket No. 70-3103


Subject: Supplement to Notice of Violation Reply LES-10-00067, Reply to Notice of Violation 70-3101/2010-007.

Reference: Letter from LES to NRC, LES-10-00067, Reply to Notice of Violation 70-3101/2010-007, dated April 12, 2010.


This letter provides supplemental information regarding the data submitted to the NRC in the Reply to Notice of Violation (NOV) 70-3101/2010-007. Subsequent to submittal of the Reply to the NOV, based on measurements of bolts removed from lower steelworks of Cascades 2-4, it has been determined that no elongation of bolts occurred as was noted as a possibility in the NOV reply dated April 12, 2010. After further evaluation it has been determined that lower and upper steel erection processes were the cause of the gaps found in the lower steelwork structure for the Cascades.

Should there be any questions regarding this submittal, please contact Gary Sanford, LES Director of Quality and Regulatory Affairs, at 575.394.5407.

Respectfully,



Gregory OD Smith  
Chief Operating Officer and Chief Nuclear Officer



IE07

LES-10-00068-NRC

cc:

Tyrone D. Naquin, Project Manager  
Two White Flint  
Mail Stop EBB2-C40M  
11545 Rockville Pike  
Rockville, MD 20852-2738

Deborah A. Seymour  
Chief, Construction Projects Branch 1  
Sam Nunn Atlanta Federal Center, 23 T85  
61 Forsyth Street, SW  
Atlanta, GA 30303-8931