

Comanche Peak Nuclear Power Plant, Units 3 & 4  
COL Application  
Part 2, FSAR




Figure 2.5.1-220 Faults Cutting Marble Falls Horizon A