

Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR




Figure 2.5.2-219 2.5 Hz Rock Seismic Hazard Curves for all Sources and for New Madrid Faults Alone