

50-331

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO:

Mr. James G. Keppler

FROM:

Iowa Elec. Light & Power Company
Cedar Rapids, Iowa
Ellery L. Hammond

FILE NUMBER

INCIDENT REPORT

DATE OF DOCUMENT

11/9/77

DATE RECEIVED

11/25/77

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☒ ORIGINAL
☐ COPY☒ UNCLASSIFIED

1516200

DESCRIPTION

ENCLOSURE

Reportable Occurrence on 10/11/77 concerning
"A" control building H & V standby filter
unit not initiating as required on low
inlet temperature and out-of-calibration
flow indication preventing permissive start
signal.....

PLANT NAME:

Duane Arnold
RJL 11/28/77

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:

LEAR

W/3 CYS FOR ACTION

LEG ASST.

INTERNAL DISTRIBUTION

REC FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

KNIGHT

BUTLER

HANAUER

TEDESCO

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

ROSA

L. CROCKER

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: CEDAR RAPIDS IA.

TIC:

NSIC:

ACRS (16) SENT AS CAT. B

773320120

A04


60

D. Lanham
REGULATORY DOCKET FILE COPY

50-331

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406
November 9, 1977
DAEC - 77 - 564



Mr. James G. Keppler, Director
Office of Inspection and Enforcement-Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Prompt Notification of a
Reportable Occurrence

File: A-118a

Dear Mr. Keppler:

This letter, telecopied to your office, is intended to satisfy the requirement for prompt notification of a Reportable Occurrence in accordance with Specification 6.11.2.a of the Duane Arnold Energy Center Technical Specifications.

Technical Specification paragraph(s) violated: 3.10.A.3

Description Occurrence: On October 11, 1977, "A" control building H&V standby filter unit did not initiate as required on low inlet temperature. Out-of-calibration flow indication prevented permissive start signal. Same problem identified on "B" standby filter unit. Originally classified as 30-day report but has now been reevaluated as 14-day report.

Very truly yours,

EL Hammond

Ellery L. Hammond
Chief Engineer
Duane Arnold Energy Center

ELH/DLW/ab

Director, Management Information and Program Control (2)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

773320120

NOV 17 1977

RECEIVED DOCUMENT
CLOSING UNIT

1977 NOV 23 PM 4 00