

50-331

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

ENVIRO

TO:

Mr. Edson G. Case

FROM:

IOWA ELEC. LIGHT & PWR. CO.
Cedar Rapids, Iowa
Ellery L. Hammond

DATE OF DOCUMENT

11/29/77

DATE RECEIVED

12/9/77

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☐ ORIGINAL☒ UNCLASSIFIED☒ COPY

100

DESCRIPTION

Licensee Event Report (Environ. 77-07) on
11/20/77 concerning liquid and airborne
effluent radiation monitor sensor checks
being inadvertently not performed.....

ENCLOSURE

PLANT NAME : Duane Arnold
RJL 12/9/77

(2-P)

SAFETY

FOR ACTION/INFORMATION

ENVIRONMENTAL

ASSIGNED AD:

BRANCH CHIEF:

[7]

LEAR

ASSIGNED AD:

V. MOORE (LTR)

BRANCH CHIEF:

PROJECT MANAGER:

PROJECT MANAGER:

LIC. ASST:

LIC. ASST:

B. HARLESS

INTERNAL DISTRIBUTION

REG FILES

NRC PDR

I & E (12)

OELD

GOSSICK & STAFF

HANAUER

MIPC

CASE

BOYD

SYSTEMS SAFETY

R. MATTSON

SCHROEDER

ENGINEERING

KNIGHT

BOSNAK

SIHWEIL

PAWLICKI

PLANT SYSTEMS

TEDESCO

BENAROYA

LATNAS

IPPOLITO

F. ROSA

OPERATING REACTORS

STELLO

EISENHUT

SITE SAFETY &

ENVIRON ANALYSIS

DENTON & MULLER

CRUTCHFIELD

ENVIRON TECH

ERNST

BALLARD

YOUNGBLOOD

PROJECT MANAGEMENT

SKOVHOLT

P. COLLINS

HOUSTON

MELTZ

HELTEMES

SK

REACTOR SAFETY

ROSS

NOVAK

ROSZTOCZY

CHECK

AT & I

SALTZMAN

RUTBERG

SHAO

BAER

BUTLER

GRIMES

L. CROCKER

SITE TECH

GAMMILL (2)

SITE ANALYSIS

VOLLMER

BUNCH

J. COLLINS

KREGER

EXTERNAL DISTRIBUTION

LPDR: CEDAR RAPIDS

TIC

NSIC

REG V (J. HANCHETT)

1 COPY SENT CATEGORY

NAT LAB: ANL

B TO ACRS

CONTROL NUMBER

773430030

Env. 1


60

D. Latham

REGULATORY DOCKET FILE COPY

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406
November 29, 1977
DAEC-77-587



Mr. Edson G. Case, Acting Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
1717 H. Street N.W.
Washington, D.C. 20545

Re: Duane Arnold Energy Center
Subject: Environmental Technical Specification
Violation Report 77-07
File: A-117

Dear Mr. Case:

This report is submitted in accordance with the requirements of Appendix B to Operating License DPR-49, Specification 5.4.2.1.

Problem

On November 20, 1977, liquid and airborne effluent radiation monitor sensor checks were inadvertently not performed.

Investigation

Sensor checks are normally performed by Chemistry Department Personnel on weekdays and by the Radwaste Operators on weekends. Due to an oversight, the on-duty Radwaste Operators failed to perform sensor checks on the above date. No abnormalities were identified when the sensor checks were performed the next day.

Corrective Action

Plant personnel involved will be instructed on the requirements for performing daily sensor checks. In addition, a step has been added to the Operations Daily Shift Instrument Checks requiring verification that sensor checks have been performed.

DEC 5 1977

773430030

Mr: Edson G. Case

Page 2

November 29, 1977

This report has been reviewed and approved by the DAEC Operations Committee and Safety Committee.

Very truly yours,

Ellery L. Hammond

Ellery L. Hammond

Chief Engineer

Duane Arnold Energy Center

ELH/DLW/nf

cc: ~~Mr.~~ J. Keppler

RECEIVED DOCUMENT
121 GNS UNIT

977 DEC 8 PM 12 00