

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9208040087 . DOC.DATE: 92/07/24 NOTARIZED: NO DOCKET #  
 FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331  
 AUTH.NAME AUTHOR AFFILIATION  
 FRANZ,J.F. Iowa Electric Light & Power Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 MURLEY,T.E. Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Duane Arnold Energy Center Unit 1 Palo,Iowa  
 Inservice Insp Summary Rept for 900911 through 920427."

*See Report*

DISTRIBUTION CODE: A047D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2+130  
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

## NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES		
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL	
	PD3-3 LA		1	0		PD3-3 PD		1	1	
	SHIRAKI,C.		2	2						
INTERNAL:	ACRS		6	6		NRR/DET/ECMB 9H		1	1	
	NRR/DET/EMEB 7E		1	1		NUDOCS-ABSTRACT		1	1	
	OC/LEMB		1	0		OGC/HDS2		1	0	
	REG FILE 01		1	1		RES MILLMAN,G		1	1	
	RES/DSIR/EIB		1	1						
EXTERNAL:	EG&G BROWN,B		1	1		EG&G RANSOME,C		1	1	
	NRC PDR		1	1		NSIC		1	1	

## NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 19

MA-2  
 JEP

Iowa Electric Light and Power Company

July 24, 1992  
NG-92-3268

JOHN F. FRANZ, JR.  
VICE PRESIDENT, NUCLEAR  
Dr. Thomas E. Murley, Director  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Station P1-137  
Washington, DC 20555

Subject: Duane Arnold Energy Center  
Docket No: 50-331  
Op. License No: DPR-49  
DAEC Inservice Inspection Report  
Reference: 1) NUREG-0313, Revision 2, "Technical  
Report on Material Selection and  
Processing Guidelines for BWR  
Coolant Pressure Boundary Piping,"  
January 1988  
2) NUREG-0619, "BWR Feedwater Nozzle  
and Control Rod Drive Return Line  
Nozzle Cracking," November 1980  
3) ASME Section XI "Rules for  
Inservice Inspection of Nuclear  
Power Plant Components", 1980  
Edition including Winter 1981  
Addenda  
File: A-107a, A-286a, B-31c, SpF-118

Dear Dr. Murley:

In accordance with the requirements of Paragraph IWA-6230 in Section XI of the ASME Boiler and Pressure Vessel Code and 10 CFR Section 50.55a(g), we herewith submit our 1992 Refueling Outage Inservice Inspection Summary Report. This report addresses examinations which were performed at the Duane Arnold Energy Center (DAEC) during the time period from September 11, 1990 (1990 Refueling Outage Startup) through April 27, 1992 (1992 Refueling Outage Startup).

Attachment 2 provides information regarding augmented inservice inspections performed during the 1992 Refueling Outage including those required by References 1 and 2.

Our review of the inspection reports has determined that all examined items are acceptable. These inspection reports are on file and are available for your review upon request.

9208040087 920724  
PDR ADDCK 05000331  
Q PDR

Dr. Thomas E. Murley  
July 24, 1992  
NG-92-3268  
Page 2

Should you have any questions regarding the attached information,  
please contact this office.

Very truly yours,



John F. Franz, Jr.  
Vice President, Nuclear

JFF/SRC/pjv~

Attachments: 1) Inservice Inspection Report (September 11,  
1990 through April 27, 1992)  
2) Augmented Inspection Report for DAEC 1992  
Refueling Outage

cc: S. Catron  
L. Liu  
L. Root  
R. McGaughy  
C. Shiraki (NRC-NRR)  
A. Bert Davis (Region III)  
NRC Resident Office  
Commitment Control No. 920089  
DCRC  
W. Mueller (ANII) (w/o)