

50-263

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO:

Mr. J. G. Keppler

FROM:

Northern States Power Company
Minneapolis, Minnesota
L. O. Mayer

DATE OF DOCUMENT

8/24/76

DATE RECEIVED

8/27/76

☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

One signed copy

DESCRIPTION

Ltr. trans the following:

ACKNOWLEDGED

DO NOT REMOVE

(1-P)

PLANT NAME:

Monticello

ENCLOSURE

Licensee Event Report (RO 50-263/76-10)
on 7/25/76 concerning failure of
containment isolation valve to close.

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

8/27/76

R.JL

☒ BRANCH CHIEF: Ziemann
W/3 CYS FOR ACTION
☒ LIC. ASST.: Diggs
W/1 CYS
ACRS 16 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

☒ REG FILE
☒ NRC PDR
☒ I & E (2)
☒ MIPC
☒ SCHROEDER/IPPOLITO
☒ HOUSTON
☒ NOVAK/CHECK
☒ GRIMES
☒ CASE
☒ BUTLER
☒ HANAUER
☒ TEDESCO/MACCARY
☒ EISENHUT
☒ BAER
☒ SHAO
☒ VOLLMER/BUNCH
☒ KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

☒ LPDR: Minneapolis, MN.
☒ TIC:
☒ NSIC:

CONTROL NUMBER


8692



NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

August 24, 1976



Mr J G Keppler, Director, Region III
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No 50-263 License No DPR-22

Failure of Containment Isolation Valve to Close


The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

Yours very truly,

L O Mayer, PE
Manager, Nuclear Support Services

LOM/DMM/deb

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
G Charnoff
MPCA
Attn: J W Ferman



REGULATORY DOCKET FILE COPY

8692

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 M N M N P 1										LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0										LICENSE TYPE 4 1 1 1 1					EVENT TYPE 0 3	
7	8	9	14	15	25	28	30	31	32																	
01		CON'T		CATEGORY 57 58		REPORT TYPE 59		REPORT SOURCE 80		DOCKET NUMBER 0 5 0 - 0 2 6 3					EVENT DATE 0 7 2 5 7 6					REPORT DATE 0 8 2 4 7 6						
7	8	57	58	59	80	81	68	69	74	75	80															

EVENT DESCRIPTION

02 DURING TEST, TORUS PURGE INLET VALVE, AO-2381, FAILED TO CLOSE. VALVE CLOSED ON																			
03 SIXTH ATTEMPT. VISUAL INSPECTIONS PRIOR TO AND DURING SUBSEQUENT CLOSURES DISCLOSED																			
04 NO ABNORMALITIES. VALVE PLACED ON INCREASED SURVEILLANCE PROGRAM. REDUNDANT																			
05 ISOLATION VALVES WERE OPERABLE AT THE TIME OF THE OCCURRENCE. NO PREVIOUS SIMILAR																			
06 OCCURRENCES (M RO-76-10).																			

SYSTEM CODE 07 S D		CAUSE CODE E		COMPONENT CODE V A L V O P				PRIME COMPONENT SUPPLIER A		COMPONENT MANUFACTURER F 1 3 0				VIOLATION N	
7	8	9	10	11	12	13	17	43	44	47	48				

CAUSE DESCRIPTION

08 CAUSE UNKNOWN. VALVE PLACED ON INCREASED SURVEILLANCE PROGRAM.																			
09																			
10																			

FACILITY STATUS 11 E		% POWER 1 0 0		OTHER STATUS NA		METHOD OF DISCOVERY B		DISCOVERY DESCRIPTION NA	
7	8	9	10	12	13	44	45	48	80
FORM OF ACTIVITY RELEASED 12 Z		CONTENT OF RELEASE Z		AMOUNT OF ACTIVITY NA		LOCATION OF RELEASE NA			
7	8	9	10	11	44	45			

PERSONNEL EXPOSURES

NUMBER 13 0 0 0		TYPE Z		DESCRIPTION NA		NA	
7	8	9	11	12	13		

PERSONNEL INJURIES

NUMBER 14 0 0 0		DESCRIPTION NA	
7	8	9	11 12

OFFSITE CONSEQUENCES

15 NA									
7	8	9							

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z		DESCRIPTION NA	
7	8	9	10

PUBLICITY

17 NA									
7	8	9							

ADDITIONAL FACTORS

18 NA									
7	8	9							

19									
7	8	9							

NAME: RICHARD GORANSON

PHONE: 612-295-5151