

50-263

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO:

Mr. J. G. Keppler

FROM:

Northern States Pwr. Company
Minneapolis, Minnesota
L. O. Mayer

DATE OF DOCUMENT

7/11/77

DATE RECEIVED

7/18/77

☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 CC

DESCRIPTION

DO NOT REMOVE**ACKNOWLEDGED**

PLANT NAME:

Monticello

(1-P)

RJL 7/18/77

ENCLOSURE

Licensee Event Report (RO 50-263/77-14) on
6/27/77 concerning air ejector radiation
monitors being found inoperable following a
startup after an outage.....NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

1 CY ENCL Rec'd

FOR ACTION/INFORMATION

BRANCH CHIEF:

Davis

W/ 3 CYS FOR ACTION

LIC ASST.:

Diggs

INTERNAL DISTRIBUTION

REG FILE

NRC-PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

KNIGHT

BUTLER

HANAUER

TEDESCO

EISENHIT

BAER

SHAO

VOLLMER/RUNCH

KREGER/ J. COLLINS

ROSA

EXTERNAL DISTRIBUTION

LPDR: **MINNEAPOLIS, MN.**

TIC:

NSIC:

ACRS (16) SENT AS CAT. B

CONTROL NUMBER

771990261

D. Lanham IE

NSP


NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

July 11, 1977

Regulatory

File 67



Mr. J G Keppler, Director, Region III
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Air Ejector Radiation Monitors Found Inoperable
Following a Startup After an Outage

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

Yours very truly,

M H Datt / for

L O Mayer, PE
Manager of Nuclear Support Services

LOM/MHV/deh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
G Charnoff
MPCA
Attn: J W Ferman

JUL 14 1977

771990261

-over-

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	M	N	M	N	P	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1		
7	8	9				14	15									25	26				30	31	32			

CONT		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE							
01				T	L	0	5	0	-	0	2	6	3	0	6	2	7	7	7	0	7	1	1	7	7
7	8	57	58	59	60	61							68	69				74	75					80	

EVENT DESCRIPTION

02	DURING PLANT STARTUP, THE AIR EJECTOR SAMPLE MONITORING SYSTEM EXPERIENCED AIR	80
03	IN-LEAKAGE CAUSED BY A VALVE BEING OPEN WHICH IS NORMALLY CLOSED. THIS CAUSED BOTH	80
04	AIR EJECTOR MONITORS TO INDICATE LOWER THAN NORMAL. VALVE WAS CLOSED AND SYSTEM	80
05	RETURNED TO NORMAL. NOT A REPETITIVE OCCURRENCE. (M-RO-77-14)	80
06		80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION	
0	7	M	C	V	A	L	V	B	X	N	G	0	8	0	Y
7	8	9	10	11					12	13	14	15	16	17	

CAUSE DESCRIPTION

08	IMPROPERLY TAGGED VALVE APPARENTLY CAUSED OPERATOR DURING STARTUP PROCEDURE TO OPEN THE	80
09	WRONG VALVE. VALVE TAGGING ON ALL OFF-GAS SAMPLE SYSTEM VALVES TO BE REVIEWED AND	80
10	CHECKED.	80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	C	0	4	0	NA	A	CONTROL ROOM OPERATOR		
7	8	9	10	12	13	44	45	46	80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	3	NA			NA			
7	8	9	10	11	44	45			80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	NA

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	0	0	NA

OFFSITE CONSEQUENCES

15	NA
7 8 9	80

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	Z	NA

PUBLICITY

17 NA 1977 JUL 18 PM 12 28

ADDITIONAL FACTORS

18 NA 8-9

19

NAME: R. D. JACOBSON

PHONE: 612/295-5151