

**AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL**  
(TEMPORARY FORM)

CONTROL NO: 8180

FILE:

<b>FROM:</b> Northern States Power Company Monticello, Minnesota 55362 C. B. Larson		<b>DATE OF DOC</b> 8-7-74	<b>DATE REC'D</b> 8-7-74	<b>LTR</b>	<b>TWX</b> X	<b>RPT</b>	<b>OTHER</b>
<b>TO:</b> Mr. Keppler		<b>ORIG</b> 1	<b>CC</b>	<b>OTHER</b>	<b>SENT AEC PDR</b> X <b>SENT LOCAL PDR</b> X		
<b>CLASS</b>	<b>UNCLASS</b> XXXX	<b>PROP INFO</b>	<b>INPUT</b>	<b>NO CYS REC'D</b> 1	<b>DOCKET NO:</b> 50-263		
<b>DESCRIPTION:</b> Facsimile, reporting an Abnormal Occurrence on 8-6-74, concerning the failure of HPCI turbine stop valve to open.....				<b>ENCLOSURES:</b>			
<b>PLANT NAME:</b> Monticello				<b>Do Not Remove</b>			

FOR ACTION/INFORMATION

8-7-74

AB

BUTLER (L)	SCHWENCER (L)	✓ ZIEMANN (L)	REGAN (E)
W/ CYS	W/ CYS	W/ 7 CYS	W/ CYS
CLARK (L)	STOLZ (L)	DICKER (E)	
W/ CYS	W/ CYS	W/ CYS	W/ CYS
TARA (L)	VASSALLO (L)	KNIGHTON (E)	
W/ CYS	W/ CYS	W/ CYS	W/ CYS
KNIEL (L)	PURPLE (L)	YOUNGBLOOD (E)	
W/ CYS	W/ CYS	W/ CYS	W/ CYS

**INTERNAL DISTRIBUTION**

✓ <u>REG FILE</u>	<u>TECH REVIEW</u>	DENTON	<u>LIC ASST</u>	<u>A/T IND</u>
✓ AEC PDR	HENDRIE	GRIMES	✓ DIGGS (L)	BRAITMAN
✓ OGC	SCHROEDER	GAMMILL	GEARIN (L)	SALTZMAN
✓ MUNTZING/STAFF	✓ MACCARY	KASTNER	GOULBOURNE (L)	B. HURT
✓ CASE	✓ KNIGHT	BALLARD	KREUTZER (E)	
GIAMBUSSO	✓ PAWLICKI	SPANGLER	LEE (L)	<u>PLANS</u>
BOYD	✓ SHAO		MAIGRET (L)	MCDONALD
MOORE (L)(LWR-2)	✓ STELLO	<u>ENVIRO</u>	REED (E)	CHAPMAN
DEYOUNG (L)(LWR-1)	✓ HOUSTON	MULLER	SERVICE (L)	DUBE w/input
SKOVHOLT (L)	✓ NOVAK	DICKER	SHEPPARD (L)	E. COUPE
✓ GOLLER (L)	✓ ROSS	KNIGHTON	SLATER (E)	
P. COLLINS	✓ IPPOLITO	YOUNGBLOOD	SMITH (L)	✓ D. THOMPSON (2)
DENISE	✓ TEDESCO	REGAN	TEETS (L)	✓ KLECKER
<u>REG OPR</u>	✓ LONG	PROJECT MGR	WILLIAMS (E)	✓ EISENHUT
✓ FILE & REGION (3)	✓ LAINAS		WILSON (L)	
✓ MORRIS	✓ BENAROYA	HARLESS		
✓ STEELE	✓ VOLLMER			

**EXTERNAL DISTRIBUTION**

✓ 1 - LOCAL PDR Minneapolis, MN.	(1)(2)(10)-NATIONAL LABS	1-PDR-SAN/LA/NY
✓ 1 - TIC (ABERNATHY)	1-ASLBP(E/W Bldg, Rm 529)	1-BROOKHAVEN NAT LAB
✓ 1 - NSIC (BUCHANAN)	1-W. PENNINGTON, Rm E-201 GT	1-G. ULRIKSON, ORNL
1 - ASLB	1-B&M SWINEBROAD, Rm E-201 GT	1-AGMED (RUTH GUSSMAN)
1 - P. R. DAVIS	1-CONSULTANTS	Rm B-127 GT
✓ 16 - ACRS <del>XXXXXX</del> SENT TO LIC ASST.	NEWMARK/BLUME/AGBABIAN	1-RD. MUELLER, Rm F-309
R. DIGGS FOR DIST		GT

**NSP****NORTHERN STATES POWER COMPANY****Monticello, Minnesota 55362****August 7, 1974**

**Mr. J. G. Keppler, Regional Director  
Directorate of Regulatory Operations  
Region III  
United States Atomic Energy Commission  
799 Roosevelt Road  
Glen Hill, Illinois 61037**

**Dear Mr. Keppler:**

**MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-263 License No. DFR-22  
Failure of HPCI Turbine Stop Valve to Open**


On August 6, 1974, during performance of routine surveillance testing, the HPCI Turbine Stop Valve failed to open. After repeated attempts the valve functioned normally. Investigation into the problem is continuing.

**Yours very truly**

**C. E. Larson  
Plant Manager  
Monticello Nuclear Generating Plant**

**CEL/kik**

**cc: J. R. O'Leary  
G. Charnoff  
Minnesota Pollution Control Agency  
Attn: E. A. Pryzina  
File**



**Copies sent by telecopier to Keppler and O'Leary**

**8180****8150**