

ACCESSION NBR: 7908090565 DOC. DATE: 79/08/06 NOTARIZED: NO DOCKET #
 FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH. NAME AUTHOR AFFILIATION
 NOLAN, L.L. Northern States Power Co.
 RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: LER 79-014/03L-0 on 790709: water leak discovered in 1/2 inch
 instrument line from reactor water cleanup sys
 nonregenerative heat exchanger. Cause not determined. Leaking
 line isolated & will be further investigated & repaired.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: INCIDENT REPORTS

NOTES: _____

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
	05 BC <i>ORB #3</i>	4	4			
INTERNAL:	01 <i>REG FILE</i>	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 KREGER	1	1	25 PWR SYS BR	1	1
	26 AD/SITE ANAL	1	1	27 OPERA LIC BR	1	1
	28 ACCIDENT ANALYS	1	1	29 AUX SYS BR	1	1
	E JORDAN/IE	1	1	HANAUER, S.	1	1
	I&C SYS BR	1	1	TMI-H STREET	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

AUG 10 1979

ad4
CCO

TOTAL NUMBER OF COPIES REQUIRED: LTTR 49 ENCL 49

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

August 6, 1979

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Instrument Line Leakage

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.d in that it represents degradation of piping designed to contain radioactive material resulting from the fission process.

Yours very truly,

David M. Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/jh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

-over-

*A002
S 1/1*

7908090560

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	6	3	7	0	7	0	9	7	9	8	0	8	0	6	7	9	9
60	61									68	69						74	75						80
DOCKET NUMBER											EVENT DATE						REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

09		SYSTEM CODE C G 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMPONENT CODE Z Z Z Z Z 14		COMP. SUBCODE Z 15		VALVE SUBCODE Z 16	
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER 17		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 0 1 4		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0			
21	22	23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN X 18		FUTURE ACTION X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. N 24	
33	34	35	36	37	38	39	40	41	42	43	44	45	46
PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER Z 9 9 9 26											
47	48	49	50	51	52	53	54	55	56	57	58	59	60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (21)

FACILITY STATUS (28) 1 5 E 28 1 0 0 (29) NA (30) 35
 % POWER OTHER STATUS
 ACTIVITY CONTENT RELEASED OF HELFSE AMOUNT OF ACTIVITY (35)
 1 6 Z (33) Z (34) NA
 PERSONNEL EXPOSURES
 NUMBER TYPE DESCRIPTION (39)
 1 7 0 0 0 (37) Z (38) NA
 PERSONNEL INJURIES
 NUMBER DESCRIPTION (41)
 1 8 0 0 0 (40) NA
 LOSS OF OR DAMAGE TO FACILITY (43)
 TYPE DESCRIPTION
 1 9 Z (42) NA
 PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 Z (44) NA
 METHOD OF DISCOVERY (32) B (31) OPERATOR OBSERVATION
 DISCOVERY DESCRIPTION (32)
 LOCATION OF RELEASE (36) NA
 NRC USE ONLY

PHON 612/295-5151

7908090565